The following items have been identified as per an existing survey of the building. We have hightlighted the following that would be repaired as part of the proposals. Fire engineer to be consulted to inspect works meet requirements for Building Regulations.

All new fire shutters must be fire tested and compliant to latest standard BS EN 16034:2014 & CE Marked to BS EN 13241-1:2003

NOTES:

nis drawing is not a working drawing, and

A- Planning Submission

The main contractor is responsible for Informulation the lead designer of any discrepency on, or between this drawing and any other relevant

All existing walls, foundations and lintels or othe structural items are to be confirmed load bearing

Any existing walls to be removed are to be

Boundaries, angles, and dimensions are checked by the main contractor prior to v

Written dimesions only to be used from this drawing. If in doubt consult the lead designer









Unit 2 Beswick St.

M8:	3	M83 Associates Ltd.	Water Street, Manchesi www.midassociates.or 1:07470 671 2 e: info@midassociates.or	
Client				
Feed My (City			
Project Tit	le			
Unit 2 Be	swick Stre	et, Manche	ster, M4 7HR.	
Drawing Title				
-	graphs A3	i		
-	graphs A3		Rev	
Site Photo	ographs A3		Rev	
Site Photo Drawing No. P1	Date			
Site Photo Drawing No. P1	Date Created By		Planning	
Site Photo Drawing No. P1	Date		Planning Building Control	
Site Photo Drawing No. P1	Date Created By		Planning Building Control Client	