CONCEPT STRUCTURAL SCHEME

NEW STRUCTURE - ALTERATION WORKS

New steel post within replacement masonry pier


(B) New steel beam

Sheathed timber stud wall

New steel eaves beam

New steel floor beam

New timber floor joists as noted on plan



INSPECTION, REMEDIAL AND REPAIR WORKS

The following is given as a guide to remedial works for tender purposes only, the contractor should undertake a site visit to satisfy themselves of the extent of works as part of the tender process.

TIMBER MATERIAL CONDITION

Material condition of all existing timber members along with condition of timber purlins, beams and joist end bearings into masonry walls or pockets into spine beam to be examined once all finishes are removed.

Extent of any decay to be established prior to confirming suitable repair or replacement like for like.

Condition of timber purlin, beam and joist end bearings / pockets into spine beam to be examined, repair as necessary. Example solutions indicated are to be confirmed at construction stage.

MASONRY CONSOLIDATION


All existing loadbearing masonry elements are to be examined for material defect replace with similar units and mortar type ensuring all voids are filled / consolidated.

Ensure to consolidate masonry under bearings of structural members

Rake out defective mortar and re-point in lime base mortar to match existing

STEELWORK / CONCRETE

Existing steel or concrete elements are to be examined for material defect or replaced.



GABLE ELEVATION

INITIAL ISSUE

INITIAL ISSUE DRAWING ISSUED FOR DISCUSSION AND COMMENT ONLY -

TENDER ISSUE DRAWING ISSUED FOR COSTING ONLY - INFORMATION NOT TO BE


BUILDING REGS ISSUE DRAWING TO BE INCLUDED IN THE BUILDING REGULATION

CONSTRUCTION ISSUE DRAWING TO BE USED BY THE RELEVANT CONTRACTOR ON SITE

SWISS COTTAGE BROGYNTYN ESTATE

CONCEPT SCHEME STRUCTURAL ARRANGEMENTS

PAPER SIZE: 1:50 20/04/2021 A1 21104/11



FIRST FLOOR STRUCTURAL ARRANGEMENT

SHOWING GROUND FLOOR WALLS UNDER