



**Part Discharge of Condition 6 of
Listed Building Consent, DC/21/04315**

for

External Wall Repairs

to

**Woodlands Farm
Bildeston Road
Ringshall
IP14 2LY**



RICS

14, Cornard Road
Sudbury
Suffolk CO10 2XA

Condition 6

INTRODUCTION

This condition required details of repairs associated with re-rendering of external walls to be agreed.

REPAIRS AND INTERNAL LINING

A separate prior application was approved for part discharge of this condition covering repairs and internal lining, DC/22/00331.

REPAIRS TO EXISTING STUDWORK

Following removal of the existing cement render external studwork faces, not previously exposed, will be repaired if required.

Removal of the internal linings identified a few areas of splice repair to stud ends which has been carried out.

EXTERNAL RENDER

Existing studwork will be clad with 50mm thick Savolit Plus wood fibre boards, all in accordance with the manufacturers recommendations.

The new render will be a 2 coat system following recommendations for Best of Lime in Haverhill. Warmcote scratch coat followed by Limecote topcoat, all to manufacturers recommendations.