

This document references the following file:-

Reference Name	Status	Revision
PC-XX-XX-M3-Designer-0001_5649		P01.1

Revisions	Date	Drawn / Chk'd
P01 First Issue	30/03/23	AO / MG



5) Replace missing or damaged soleplate.
Note - Replace from present plate joint.



5) Replace missing or damaged soleplate.



7) Replace missing corner post.



4) Trim door opening with oak subframe.



5) Replace missing or damaged soleplate.



5) Replace missing or damaged soleplate.
6) Re-tenon studs and post and fit to new plate.

Client

Mr R. Eldridge

Project

Proposed Extension and Internal Alterations to
The Pheasantry, Wattisham

Title

Timber Frame Repairs

Project N^o Drawing N^o Revision

5649 - 0511 P01

Scale - unless otherwise stated Issued For

N / A @ A3 PRELIMINARY

BS 1192 Ref. Status

PC-Designer-0511