


- 1) Splice lower end and rafters.
- 2) Remove fletton brick infill.
- 3) Replace rotten sole plate on raised position - Tenon fit existing studs.
- 4) Trim door opening with oak subframe.
- 5) Replace missing or damaged soleplate.
- 6) Re-tenon studs and post and fit to new plate.
- 7) Replace missing corner post.



Client

Mr R. Eldridge

Project

Proposed Extension and Internal Alterations to The Pheasantry, Wattisham

Title

Timber Frame Repairs

Project N° Drawing N° Revision

5649 - 0510 P01

Scale - unless otherwise stated Status Issued For

1 : 50 @ A1 PRELIMINARY

BS 1192 Ref.

PC-Designer-0510