



Photo: 1

Lounge showing
ceiling & the 2
internal doors. Also
internal wall.



Top ↑

Photo 2:
External wall.



Photo 3:

Kitchen showing
existing boarded
ceiling



107 11

Photo 4:

Lounge ceiling was
lath + plaster. To be
replaced with the
same.