

**Hoare, Ridge & Morris Architects**  
23 October 2023  
Timber Frame Review  
South Elevation of West Crosswing

Decayed Corner Post:  
(Refer to notes on west elevation)

Weak / Decayed Studs:  
Partner 75mm(w) x 75mm(d) x  
700mm(h) studs to 3no. existing  
decayed studs.

Decayed Sole Plate:  
Severely decayed sole plate requires  
replacement. New sole plate to match size  
of what existing used to be: 175mm(h) x  
125mm(d). To include mortices for post  
tenons where they are remain.

Remove concrete fillet and reduce plinth height  
(Refer to 210. PL20)