

View from Glenshee Road looking at existing site entrance





5. View of existing perimeter stone wall with metal railings at lane



7. View of existing lane and existing stone perimeter wall to be repaired following fire



2. View from on site looking towards site entrance





6. View looking across the as existing site from existing lodges



7. View of existing lane and existing stone perimeter wall to be repaired following fire

RE DATE DESCRIPTION

ALL DIMENSIONS TO BE CHECKED ON SITE
DO NOT SCALE FROM THIS DRAWING.
USE FIGURED DIMENSIONS ONLY.
IF IN DOUBLY ASK.
THIS DRAWING IS THE COPYRIGHT OF CRGP LTD. AND SHOULD NOT BE
REPRODUCED IN ANY FORMAT WITHOUT PRIOR APPROVAL.

CRGP Limited Unit 9 The Green House Beechwood Business Park Inverness IV2 3BL	WANTED MOSESTANDS JEMAST SEE: TÜPAST SEP Jaga, Badayan
also in Glasgow	

Tel: 01463 718 200 web: www.crgp.co.

CLIENT

Braigh Mharr Ltd

Braemar Lodge site

Images of site as existing

ı	PLANNING					
	DRAWN	JS	SCALE	NTS		
ı	CHECKED	BMcF	ORIGINAL	A3		
ı	JOB NO.	102-0197	DATE	Oct 2023		

PL (00) 003

	1 1	•	• 4		
${m hinspace}$	'hatas	\cap †	SITA	25	existing
	110103	O1	Sito	as	Chisting