

CRACK MONITORING

for Subsidence Management Services

8 Taylers Cottages, Potters Bar, EN6 3LL

Client:	Subsidence Management Services
Client Contact:	Ian Domigan
Claim Number:	500401678
Client Reference:	IFS-LBG-SUB-22-0104199
Policy Holder:	Mr Trevor Williams
Report Date:	14 July 2023
Our Ref:	M20164


Crack Monitoring Readings

The following table shows the reading levels of the Crack Monitoring Stations.

Date	A=B (H)	B=C (D)	A=C (V)(C)	Crack Width
C1 - EXT - Lintel above NO7 front door				
24 January 2023	110.40	115.90	50.67	8.90 - 7.30
23 February 2023	109.97	115.64	50.67	7.00 - 21.40
23 March 2023	109.90	115.51	50.59	
19 May 2023	109.19	114.86	50.54	6.80 - 20.70
15 June 2023	109.12	114.84	50.57	
13 July 2023	109.78	115.41	50.75	7.70 - 2.20

Crack Monitoring Difference Graphs

The following graphs display the progressive movement that each Crack Monitoring Station recorded at each separate site visit date to give an overall look at how much the property is moving.



Site Visit Notes

Site Visit: 28 December 2022

Tech advise site plan isn't correct as looks like requested stud is wanted next door and unable to get permission from them. Please advise if still needed.