

Pardon Chambers Architects

1-3 Ash Cottages, Albury Road, Little Hadham, SG11 2DQ

Window and Door Schedule (to be read in conjunction with drawing: Ash Cottages- Window and Door references)

MAIN HOUSE GROUND FLOOR

D0.1 Front elevation external door: repair and paint

D0.2 Front elevation external door: repair and paint

D0.3 Front elevation external door: repair and paint

D0.4 Rear elevation NEW external door: glazed, painted timber with NO middle rail (single panel) Drawing 2501

D0.5 Rear elevation NEW external door: glazed, painted timber with NO middle rail (single panel) Drawing 2501

D0.6 Rear elevation NEW external door: glazed, painted timber with NO middle rail (single panel) Drawing 2501

D0.7 Rear elevation NEW external French doors: glazed, painted timber with NO middle rail (single panel) Drwg 2502

D0.8 NEW internal door: glazed, painted timber (four panel) Drawing 2504

D0.9 internal door: repair and paint

D0.10 internal door: repair and paint

D0.11 internal door: repair and paint

D0.12 internal door: repair and paint

D0.13 internal door: repair and paint

D0.14 internal door: repair and paint

D0.15 internal door: repair and paint

D0.16 NEW internal door to wc: painted timber (four panel) Drawing 2503

D0.17 NEW internal door to wc: painted timber (four panel) Drawing 2503

W0.1 Front elevation window: repair and paint, add secondary glazing

W0.2 Front elevation window: repair and paint, add secondary glazing

W0.3 Front elevation window: repair and paint, add secondary glazing

W0.4 Front elevation window: repair and paint, add secondary glazing

W0.5 South elevation window: repair and paint, add secondary glazing

W0.6 South elevation NEW window: painted timber, double casement, opaque heritage double glazing drawing 2314

W0.7 Rear elevation NEW window: painted timber, double casement with central fixed light, heritage double glazing drawing 2314

W0.8 Rear elevation NEW window: painted timber, double casement, heritage double glazing drawing 2314

W0.9 Rear elevation NEW window: painted timber, double casement, heritage double glazing drawing 2314

W0.10 North elevation NEW window: painted timber, double casement with horizontal glazing bar, heritage double glazing Drawing 2510

W0.11 North elevation window: repair and paint, add secondary glazing

GARAGE/ HOME OFFICE

D0.18 NEW external doors: two leaf glazed engineered oak sliding door set. Finish: sealed (type tbc) drwg 2507

D0.19 NEW external doors: two leaf glazed engineered oak sliding door set. Finish: sealed (type tbc) drwg 2507

D0.20 NEW external doors: two leaf glazed engineered oak external sliding "barn" doors. Finish: sealed (type tbc) drwg 2508

BARN/ ANNEX

D0.21 Main elevation NEW external door: glazed engineered oak door. Finish: sealed (type tbc) drawing 2509

D0.22 Side elevation NEW external door: glazed engineered oak door. Finish: sealed (type tbc) drawing 2509

W0.12 Main elevation NEW window: engineered oak, single casement, side hung, heritage double glazing drwg 2331

W0.13 Main elevation NEW window: engineered oak, single casement, side hung, heritage double glazing drwg 2331

W0.14 Main elevation NEW window: engineered oak, single casement, side hung, heritage double glazing drwg 2331

W0.15 Rear elevation NEW window: engineered oak, single casement, side hung, heritage double glazing drwg 2331

MAIN HOUSE FIRST FLOOR

W1.1 Front elevation window: repair and paint, add secondary glazing
W1.2 Front elevation window: repair and paint, add secondary glazing
W1.3 Front elevation window: repair and paint, add secondary glazing
W1.4 Front elevation window: repair and paint, add secondary glazing
W1.5 Front elevation window: repair and paint, add secondary glazing
RW1.1 Conservation roof light from The Rooflight Company drawing 2311
RW1.2 Conservation roof light from The Rooflight Company drawing 2311
RW1.3 Conservation roof light from The Rooflight Company drawing 2311

D1.1 NEW internal door: four panel painted Drawing 2503
D1.2 NEW internal door to shower room: glazed stained timber door, opaque glazing drawing 2505
D1.3 NEW internal door to family bathroom: glazed stained timber door, opaque glazing as part of glazed screen drawing 2505
D1.4 internal door: repair and paint
D1.5 internal door: repair and paint
D1.6 internal door: repair and paint
D1.7 internal door: repair and paint
D1.8 internal door: repair and paint
D1.9 NEW internal door: ledge and brace, painted 2110 2506
D1.10 internal door: repair and paint
D1.11 internal door: repair and paint
D1.12 internal door: repair and paint
D1.13 internal door: repair and paint

MAIN HOUSE SECOND FLOOR

W2.1 Front elevation window: repair and paint, add secondary glazing
W2.2 Front elevation window: repair and paint, add secondary glazing
W2.3 Front elevation window: repair and paint, add secondary glazing
RW2.1 Conservation roof light from The Rooflight Company drawing 2311

D2.1 internal door: repair and paint
D2.1 internal door: repair and paint