



2. GENERAL VIEWS OF ROOF STRUCTURE ↓ DORMER ↗



• BRICK CHIMNEYS NEED REPAIR TO ERODED BRICKS & CRACKS & TIEING TO ROOF STRUCTURE

drawing title PHOTOGRAPHS OF ROOF STRUCTURE		FREELAND REES ROBERTS ARCHITECTS 25 City Road, Cambridge, CB1 1DP tel 01223 366555 fax 01223 312882 info@frrarchitects.co.uk			
client SIMONNE GRAEUS & JAMIE CAAPPEL	job title THE GIGARE OLD NEWTON	scale — @A3	drawn HF	date NOV 2023	sheet/layout number 23.038 / ROOF PH 1
					rev



GENERAL VIEWS OF THE ROOF STRUCTURE



drawing title PHOTOGRAPHS OF ROOF STRUCTURE	FREELAND REES ROBERTS ARCHITECTS 25 City Road, Cambridge, CB1 1DP tel 01223 366555 fax 01223 312882 info@frreearchitects.co.uk			
	client SIMONNE GRAYERS & JAMIE CHAMBERS	job title THE COTTAGE OLD NEWTON	drawn HF	date Nov 2023
	scale -	sheet/layout number 23-038	REV Roof PH 2	REV



↑ CEILING WHEN SPINE BEAMS IN TWO BAYS ARE CRACKED -



• SLOPING CEILINGS ARE ON THE OUTSIDE OF THE RAFTERS.

drawing title PHOTOGRAPHS OF ROOF STRUCTURE		FREELAND REES ROBERTS ARCHITECTS 25 City Road, Cambridge, CB1 1DP tel 01223 366555 fax: 01223 312882 info@frrarchitects.co.uk				
client SIMONNE GRAEUS & JAMIE CAMPBELL	job title THE COTTAGE OLD NEWSYD.	scale — @A3	drawn HF	date NOV 2023	sheet/layout number 23-038 / ROOF PH 3	rev