



A mound has developed toward the side of the tree where it is leaning away from indicating uprooting in that area


The huge root system under ground on this side of the tree is causing this unevenness and is a clear indication of concerning uprooting movements



Significant dip in the ground giving rise to a large difference in ground level







Displacement of the entire gravel grids have started occurring in rapid time recently rather than just small cracks originally

The displacement of the gravel grids are clearly in an upwards direction rather than a horizontal direction as indicated in the pictures in Jan 22





The difference from Jan 2022 to now is huge and very clear to see.



The report done by Andrew Burden in Jan 22 specifically recommended immediate removal of all 3 Scots Pine trees.



Andrew Burden Tree Services was established in 1987. He is an arborist qualified to HND level in arboriculture and woodland management.