

Notes

Notes


This drawing is the copyright of Giles Quarme Architects and cannot be printed or reproduced without prior permission.

This drawing has been based on survey information provided by others.

All dimensions and setting out must be verified on site before commencement of the work, and any discrepancies notified to the architect.

All windows and doors are to fit into existing openings unless stated otherwise.

All dimensions are in millimetres unless stated otherwise.



2nd FLOOR LOCATION PLAN

NTS @ A3

Measured Survey
All Survey information shown indicatively only, and may not
accurately reflect dimensions on site. Main Contractor to verify all
dimensions on site and notify Architect of all discrepancies between drawings and existing dimensions.

Condition Survey:
Building to be carefully inspected following erection of scaffold.
Select fittings to be carefully removed by Client prior to
commencement of building Contract; Remaining fittings to be
carefully protected in-situ by Contractor.

External Walls:

External walls to be carefully cleaned and any hungry joints to be repointed in lime mortar. Broken bricks to be carefully cut out and replaced to match. Cementitious pointing to be carefully removed an repointed in lime mortar.

Internal Walls:
All brick walls to be carefully cleaned and brushed back. Hungry joints to be carefully repointed in lime mortar. Broken bricks to be cut out and replaced to match. All cementitious pointing to be removed. Painted walls to be carefully redecorated and existing wallpaper to be removed throughout.

<u>Decorations:</u>
The entire West wing is to be redecorated. The East wings decorations are to be made good where the services are upgraded.

<u>Services:</u>
All existing services to be carefully removed and replaced as per Services Engineers drawings and specifications.

IT Systems/ Cables and Access Control:
All cabling (data etc.) to be updated to CAT6. All redundant cabling to be removed. Access control and security systems to be installed within courtyard to allow for managed entry.

Flooring, Joinery and Stair:
Timber flooring throughout to be repaired and renewed as appropriate. All joinery to be repaired and made good as appropriat overhaul and repair of all stairs. Allow for fixing of permanent nosing strips to all stairs.



DRAFT

Rev By Date Description
Rev A MF 10.2023 Minor amendments to notes

Drawing Number

9820 T (3) 512

LONDON FO GUANG SHAN TEMPLE Job No. 9820

Typical Blind Window Details for Reused Window

Checked GQ Drawn MF Date August 2023 | Scale 1:10 @ A3

Giles Quarme Architects Historic Building Architects & Consultants

7 Bishops Terrace

020 7582 0748 www.quarme.com mail@quarme.com