



219502- DOC- 001

3/20/1051/FUL

Condition 16 – preventing surface water discharging onto Hillside Lane and Pepper Hill.

Hillside Lane Access

- A drainage gully has been installed which collects water into a drainage channel that runs along the south side of the access road and drains into a soakaway. Please see the photograph below.
- Please also refer to drawing ref 219502-PL-003



Pepper Hill Access

- There is no discharge onto Pepper Hill given that land levels fall to the east and south, therefore directing water away from Pepper Hill (as evident from drawing 219502-PL-001).