



PHOTOGRAPH 01:

Front of wall and RH gatepost reveal



PHOTOGRAPH 02:

Front wall viewed from road



PHOTOGRAPH 03:

Front wall viewed from road



PHOTOGRAPH 04:

RH side return wall with large bulge at base



PHOTOGRAPH 05:

Cracked and vegetated sand and cement capping to front wall.



PHOTOGRAPH 06:

RH Side return wall cracked and bulging



PHOTOGRAPH 07:

RH Side return wall garden side with old ivy stump



PHOTOGRAPH 08:

Rear Elevation Main House