## RIACH architects


65 Banbury Road, Oxford OX2 6PE 01865 553772 | mail@riacharchitects.com www.riacharchitects.com

> The Jam Factory 4 Hollybush Row Oxford OX1 1HU

> **Repair photographs**

December 2023





G.RM 05 - ROOM 01: Counter



G.RM 05 – ROOM 01: Walls & Floors


 ${\it architecture} \mid {\it planning} \mid {\it project management}$ 

Riach Architects Limited is registered in England and Wales, Company number: 8867519
Registered office: 65 Banbury Road, Oxford, OX2 6PE
A full list of Disch Architects Directors is available for inspections at the constant of fire.





G.RM 01 -KITCHEN: Walls



G.RM 01 - KITCHEN: Windows

 $architecture \mid planning \mid project \; management$ 

Riach Architects Limited is registered in England and Wales, Company number: 8867519
Registered office: 65 Banbury Road, Oxford, OX2 6PE
A full list of Pinals Architects Disactors in will black for inspections at the constraint of fice.





G.RM 10 – ROOM 5: Stairs removed.




F.RM 01 – Mezzanine: mezzanine removed, & walls replastered.






G.RM07 – ROOM 3: Steps removed & new flooring.



G.RM 08 – ROOM 4: Steps removed & new flooring.





G.RM 07 – ROOM 3: Wall & ceiling finish to be repaired.



G.RM 07 – ROOM 3: Courtyard entrance to be repaired.





G.RM – COURTYARD: Courtyard elevation



G.RM – STREET ELEVATION: Arch window opening made & bricks cleaned.





G.RM – External wall to be cleaned & repair where necessary.



G.RM 01 – KITCHEN: Wall finish & cable tidy





G.RM 01 – KITCHEN: Pipes & cable tidy



G.RM 10 – ROOM 5: Timber door replaced & new wall finish.





G.RM 06 – ROOM 2: Rotting roof structure to be repaired.



G.RM 08 – ROOM 4: Leaking roof repair & mould removed.





G.RM – Courtyard: Wooden gate to be repaired.



G.RM – Highstreet boundary wall: Wall cleaned & metal gates.

