

SECTION OF COLLAPSED BOUNDARY WALL AGAINST 6 BARN STREET.



SECTION OF COLLAPSED BOUNDARY WALL ADJACENT TO 6 BARN STREET.



L TREE TO BE REMOVED (BY SEPARATE APPLICATION).



SECTION OF BOUNDARY WALL BEFORE COLLAPSE. NOTE: BRICK BANDING DETAIL IS DIFFERENT IN THIS BAY. APPLIED PIER WILL NOT BE REINSTATED.

SECTION OF BOUNDARY WALL TO BE REBUILT.

တ

TREES TO BE RETAINED AND CAREFULLY MANAGED TO ALLEVIATE ROOT PRESSURE AND MOVEMENT ON THE WALL.

S

- ALL DIMENSIONS TO BE CHECKED ON SITE AND NO MEASUREMENTS TO BE SCALED OFF THIS DRAWING.
- 2. IN CASE OF ANY DISCREPANCY THE ENGINEERS ARE TO BE NOTIFIED IMMEDIATELY.
- 3. THIS DRAWING IS TO BE READ IN CONJUNCTION WITH ALL RELEVANT ARCHITECT'S AND SERVICE ENGINEER'S DRAWINGS AND SPECIFICATIONS.

PLANNING

A	LISTED BUILDING CONSENT	EJM	24.01.24
-	DRAFT ISSUE FOR COMMENT	EJM	23.01.24
-	DRAFT ISSUE FOR COMMENT	EJM	22.01.24
ĒV	AMENDMENT	снк	DATE

The Morton Partnership

- OLD TIMBER YARD HOUSE 55 THE TIMBER YARD DRYSDALE STREET, LONDON N1 6ND TELEPHONE: 0207 324 7270 EMAIL: london@themortongstbaseh's

THE GROVE LAVENHAM SUFFOLK



BOUNDARY WALL REPAIR SITE BLOCK PLAN

SCALE: 1:200 (A3) DRAWN BY: CJS

22764/02 (REV A)