



© Franklin Ellis (2022) Ltd. Company No: 14131809

Key

External Walls Strip off all unnecessary services. • Repoint where necessary, clean brickwork. Make good exposed existing walls following demolition. New areas of external wall/infill to be in brick reclaimed from elsewhere on the building/site.

<u>Roof</u>

• Overhaul turret/weathervane, make like for like repairs where necessary. Make like for like repairs with clay tiles/slates to match on pitches, hips etc. Strip off bay roof and replace with single ply membrane with applied lead rolls. Renew all leadwork, flashings etc.

<u>Doors</u>

 Assess on individual basis. Overhaul, carry out like for like repairs or replace with period appropriate replacements.


<u>Windows</u>

windows. windows to be double glazed.

<u>Timberwork</u>

Joinery

<u>Services</u>



General Notes:

- 1. Do not scale off this drawing unless a scale bar is provided. 2. Any ambiguities, omissions and errors on this drawing should be notified
- immediately to the Architect before the commencement of works on site.
- 3. Dimensions are in millimetres unless otherwise stated. 4. Dimensions, unless otherwise indicated, are to the face of unfinished block walls
- or to the finished plaster face of stud partitions. 5. Dimensions are to be checked on site. Discrepancies are to be notified
- immediately to the Architect before the commencement of works on site. 6. All levels are in meters unless otherwise stated.
- 7. This drawing is to be read in conjunction with all other relevant drawings and specifications for this project.

Revision Notes:

Rev.	Date	Notes	lssuer	Checker
Ρ1	2023-08-04	Preliminary Issue P1	IAT	JC
P2	2023-09-12	Refined layout with elevational alterations.	MJ	JC
P3	2023-10-17	Planning Submission	MJ	JC

5m 1:100

---- Proposed wall lining

GENERAL NOTES

<u>lronwork</u>

Overhaul and redecorate.

 Cap chimney. Overhaul rainwater goods replace like for like where necessary. Vent tiles to be added where necessary.

 Restore original glazing to first floor front Assess on individual basis. Overhaul, carry out like for like repairs or replace with similar – existing windows to be draught stripped, new

• Overhaul, carry out like for like repairs.

• Timber Overhaul, carry out like for like repairs.

Ventilation via opening windows.

LONDON ROAD

NEWARK

Job Number: 23-0030 **Client Name: Bildurn Properties**

Director / Associate: Matthew Branton

Status: A3 Planning Sheet Size:

A1L

Drawing Name:


Project Address: London Rd, Newark NG24 1TW

Project Lead: Sarah Boxford Functional Breakdown: B3 - Block 3 Scale:

1:100

GA Sections Proposed Sheet 2 of 2 - Block 3

Full Document Reference: Identification / Location Project Originator Function Space Form Disc. Number BLR-FEA-B3-XX-DS-A-3231



FRANKLIN ELLIS ARCHITECTS