# GENERAL NOTES

## External Walls

- Strip off all unnecessary services.
- Repoint where necessary, clean brickwork.
- Make good exposed existing walls following demolition.
- New areas of external wall/infill to be in brick reclaimed from elsewhere on the building/site.

#### <u>Ironwork</u>

• Overhaul and redecorate.

#### <u>Roof</u>

- Make like for like repairs with clay tiles/slates to match on pitches, hips etc. Strip off bay roof and replace with single ply membrane with applied lead rolls.
- Renew all leadwork, flashings etc.
- Cap chimney. Overhaul rainwater goods
- replace like for like where necessary.
- Vent tiles to be added where necessary.

### <u>Doors</u>

• Assess on individual basis. Overhaul, carry out like for like repairs or replace with period approriate replacements.

### <u>Windows</u>

- Restore original glazing to first floor front windows.
- Assess on individual basis. Overhaul, carry out like for like repairs or replace with similar – existing windows to be draught stripped, new windows to be double glazed.
- Existing windows facing London Road to be secondary glazed.

#### <u>Timberwork</u>

• Overhaul, carry out like for like repairs.

### <u>Joinery</u>

Overhaul, carry out like for like repairs.

### <u>Services</u>

- Ventilation via opening windows.
- Heating by gas boiler



© Franklin Ellis (2022) Ltd. Company No: 14131809

5

windows

Existing Painted timber frame

(10) Red ridge tiles

(15) New lead surround walls

