

Side- South Facing Elevation



replace
down
pipe
+
gutter

repoint
string
course

→ repoint / repair / replace cornice

→ repoint chimney x 2

→ repoint walls

→ replace gutter

→ School.