



Condition Report

Further to the survey of the following property it is our recommendation the windows is fully replaced, this is due the condition being beyond repair. There are signs of repair already undertaken which means retrofitting with double glazing to achieve improved insulation and noise reduction would be unsuccessful, if not counterproductive in terms of the longevity of further repairs.

5/26 Rankeillor Street, EH8 9HY

Full replacement

2 @ 6 over 6 style

Company No. SC608678
2-4 Salamander Place
Edinburgh
Scotland
EH6 7JB

Quotation valid for 60 days and is subject to company terms and conditions which are available on request