





Note to Designers and Contractors

Under the CDM2015 regulations BWA has sought to eliminate or reduce risks where possible as part of the design process.

Significant residual risks, or areas of work that require special attention during construction, which have been identified by BWA, are indicated on project drawings by the following symbol \bigwedge .

It is anticipated that other designers and contractors will co-operate to identify any potential construction hazards and to eliminate them were possible.

Measures to minimise residual hazards will be reviewed on a regular basis.



