

Original railings made good as required (including clean and repaint) and reinstated including original gate. Horizontal 'top cage' NOT

Top bar of railing (circa 40mm square) must be continuous as indicated, with full strength butt welds where previously cut for removal.



Existing railing sections. Generally appear to be in fair condition and only in need of putting back into position and welding back together, plus decorative repair. Still set into base stones, which appear adequate for reinstatement.



Extg hook support



Existing gate, frame, and spandrel panel. Requiring various repairs.

- This drawing is copyright and may not be reproduced without the permission of Mann Williams.
- All drawings are to be read in conjunction with the project specification with all works carried out in accordance with the latest British Standards and codes
- Any ambiguities or discrepancies between this drawing and any other information given elsewhere must be reported to Mann Williams for clarification before work
 - All dimensions to be checked on site and any discrepancies reported to the engineer before work
- Only figured or calculated dimensions should be used and no drawing , in any format should be scaled.

DRAFT ISSUE HP 05.12.23 HP 07.12.23 P2 ISSUE TO B&S

BRIDEWELL MAGISTRATES COURT

DESIGN INTENT FOR RAILINGS AROUND STAIR 3, IN COURTYARD



CONSULTING CIVIL AND STRUCTURAL ENGINEER 7 OLD KING STREET QUEEN SQUARE BATH BA1 2JW **T** 01225 464419 01225 448651 E bath@mannwilliams.co.uk

HP A3

PRELIMINARY

P2

DEC' 23

7768 SK79