



3 things.

1. The heritage Dormer Window man [Glen from Abbey Sash Windows] says. "We will need to replace all the wood of the actual sash window frames and the side tongues. However the Box [by which I assume he means the main structural bits] and also the runners seem okay so we will just treat and paint those.

2. When I was talking about the roof, I was only referring to the bit above the dormer and NOT the whole roof. Glen says that in fact he doesn't think we will need to touch the roof except that one side of the wood overhang is not present and will need to be replaced [this can be seen on the photos]

3. Glen has sent an plan for the structure of the replacement double glazing [attached]

Is it sufficient that I have sent you these or do I need to go back and adjust the application?





















