


Repair and replace rotten timber with spliced elements. Paint and finish as existing.

Carry out repairs to corner window casements. Cills and casements to be repaired and openings re-established.

Carry out repairs to all ground floor sash windows on south elevation.

 = Replace cills with hardwood to match existing.



Proposed South Elevation  
Scale: 1:100

