


Dear Listed Building Department.

Following that latest storm the front door at No.1 Grantlands is no longer functioning properly and needs to be replaced quickly before any further storms happen. It is west facing, rain is being driven into it and rain water is pooling inside the house. The moisture is also causing the door to warp and it is very difficult to open, close and lock securely.

Attached is a plan of the new door. We understand that this is closer in design to the original door, which the current one replaced and whose glazed units were removed, by previous owners and covered with the panels that are now falling off. (this happened before before we owned the property)

Proposed Door.



To be finished in black paint, similar to neighbouring properties. Hardware: Door handle to match existing door.

Photographs of existing front door

