

The Old Church, Mockbeggar Lane, Ibsley

Entrance Door Renewal

HERITAGE STATEMENT

- *Please refer to full heritage report in the associated planning and listed building applications for a full assessment of the building.*
- Repairs to the entrances of the building are essential to ensure the timber doors do not rot further and fail. The rear doors particularly present a security risk as they are badly rotten and could be easily kicked in by vandals/thieves.
- Existing doors are plywood core, partially metal clad to the north elevation. Doors and ironmongery are not original and likely installed in the 1990s when the building was closed as a church and opened as a gallery.
- New doors will match the existing profile in terms of size and thickness. Glazing will match existing. Doors painted black. Ironmongery black.
- There will be no visual change of the building from the existing to the proposed, except for the proposal to paint the rear doors black to match the front.
- There is no material to retain from these modern doors installations, firstly due to the condition but secondly due to them not being original.
- New doors to be high quality, handmade to size from external grade timber.

Existing door condition noted here:

