

The Old Church, Mockbeggar Lane, Ibsley

Entrance Door Renewal

DESIGN & ACCESS STATEMENT

- The existing doors are in poor condition and beyond repair. In order to protect the building and ensure the doors do not fail, new doors are proposed.
- There is no change to the site or its setting.
- Existing doors are NOT original and are cheap alternatives to what would have been there originally.
- New doors to be solid timber, as the original doors would have been.
- All materials are suitable for the work required and for the type of building, standing of the building and Listing.
- New doors to replace the poor workmanship/materials of the current installations.
- Building is currently extremely poor energy efficiency wise. New doors can incorporate brush seals to assist with draft proofing. Glazing is currently double but can be improved using a more modern alternative (same appearance).