

FFW03 W07



front elevation - 1:20



first floor plan - 1:50



external view

current condition:

estimated late C20 casement window

painted shut, unable to open

adjacent shutters in good condition, to be lightly sanded and repainted

timber window frames showing signs of rot &
ironmongery worn

expanding foam has previously been used to stop draughts, secondary glazing has also been fitted

proposed replacement unit:

2 light 1 window unit to be replaced with like for like timber unit

replacement unit to contain leadwork to match existing $% \left(1,2,...,n\right) =0$

slimline double glazing to remove the need for any further secondary glazing



internal views







Collaborating with: Linda Behan

Job: Drawing: 997 10-06

Mar 24
Revision: Drawn By:

Whitfield Farmhouse, Hungerford Lane, Shurlock Row, RG10 ONY Drawing: FFW03 W07

Checked By:

Date: Status: Mar 24 planning

Chartered Practice

Colony Architects Ltd.

The Wine Store, Brewery Court, Theale, Reading, RG7 5AJ +44 (0)118 380 0328 hello@colonyarchitects.com colonyarchitects.com

1:20 0.4m 0.8m 1.2m 1.6m 2.0m 1:50 1m 2m 3m 4m 5m