

## FFW01 W05



front elevation - 1:20



first floor plan - 1:50



external view



internal views

## current condition:

estimated late C20 casement window painted shut

fitted with internal secondary glazing

## proposed replacement unit:

2 light 1 window unit to be replaced with like for like timber unit

replacement unit to contain leadwork to match existing

slimline double glazing to remove the need for any further secondary glazing



internal views

Linda Behan





Whitfield Farmhouse, Hungerford Lane, Shurlock Row, RG10 ONY

FFW01 W05

Revision:

Mar 24 planning Drawn By: Checked By:



Colony Architects Ltd. +44 (0)118 380 0328

hello@colonyarchitects.com colonyarchitects.com