



5

PROPOSED FRONT/EAST ELEVATION
1:100

REPAIRS OR TO CHANGE
CHARACTER OF WINDOW.
WINDOWS TO MATCH EXISTING.
FOOTING TO BE CHECKED BY BOUNDARY INS.
ON SITE