

- Original Valls.

 1. Carefully remove and rub back non-original plaster marked red to reveal original brick
- Carefully strip out non-original block partition walls marked in red
- Part of the internal and perimeter walls have a ceramic tiled finish. This is not considered to be original. To be carefully cleaned and where necessary protected by internal theor frame lining
- Dividing Valli Englarge two existing openings to original dividing wall, section $\mathbb{C}-\mathbb{C}$
- Carefully strip-out non-original non-structural block wall
- Historic Vindows: Carefully carefully, ease and overhaul all retained non-original windows and repair within subject denise only.
- <u>Iniginal laors:</u> Carefully ease and overhaul retained norroriginal doors
- 8. <u>Original Beans: C</u>arefully rub down retlaned original beans and remove redundant fixings

ίο	Add section C-C This entargment to door appartures		
Client M-One Studios	indice	Date	Date 12/11/2020
	Marco	Drawn	PJK
Project No	Project North Block, Chatham Mill	Approved ??	d ??
121	128759/LO/2020	Scale 1	Scale 1:100@A3
Drawing title		Jab No.	Job No. 10029

Scanlans Consultant Surveyors LLP 3rd Floor, Boulton House, 17-21 Chorlton Street, Manchester, M1 3HY 17-016 (288 878) www.scanlans.consultantsurveyors.com