

This drawing shows indicative locations of work required, based on an aerial survey only. Detailed inspection cannot take place until suitable access is in place, and further works may be identified once a detailed inspection has taken place from the scaffold.

Cleaning brickwork of moss etc. All elevations

Render repairs to eaves in patch to match existing, all elevations.

Hammer testing / pinning to stone embellishments all elevations.

Like for like repointing in lime mortar. All elevations

Cleaning brickwork of moss etc. All elevations



FOR RAMP DETAILS REFER
DWG. H1126 PDE 601

USE FIGURED DIMENSIONS; DO NOT SCALE FROM DRAWING. ALL LEVELS AND DIMENSIONS TO BE CHECKED ON SITE. DRAWING TO BE READ IN CONJUNCTION WITH ALL RELEVANT DOCUMENTS. © HUNTER EVANS LTD. ALL RIGHTS RESERVED.

HUNTER EVANS

THE SALVATION ARMY
WILLIAM BOOTH COLLEGE

Date SEP. 2008 Drawn APL

PROPOSED GENERAL ARRANGEMENT
BUILDING 16
SECTIONAL ELEVATION JJ

Scale 1:100 @ A1 / 1:200 @ A3

CAD Ref STAGE D:\PR 434 - 444 H1126.dwg

Drawing Reference

Job No H1126 PPR 442 F

388 Oxford Street London W1C 1J5
Telephone: 020 7529 5488 Facsimile: 020 7529 5489
E-mail: mail@hunterevans.co.uk www.hunterevans.co.uk

ARCHITECTS, BUILDING CONSULTANCY AND PROJECT MANAGEMENT

