

EXISTING VILLA TEMPORARY WORKS REQUIREMENTS

RIDGE - FEB 2021

LATERAL RESTRAINT TO BE PROVIDED
TO 1ST FLOOR CILL BRICKWORK

VERTICAL SUPPORT TO BE
PROVIDED TO FAILED LINTEL

