
Material Key:

- BRICK
- DOUBLE GLAZED ALUMINIUM WINDOWS 2
- SLATE ROOF 3
- BALCONY RAILING GLASS BALUSTRADE
- TIMBER DOOR 5
- TIMBER INFILL PANEL/VERTICAL TIMBER CLADDING 6
- GALVANIZED STEEL REMOTE CONTROLLED GATE
- **RETAINING WALL** 8
- WHITE RENDER 9
- 10 CURTAIN WALL TO THE STAIRCASE



WORK IN PROGRESS 23.07.18



Notes:

1. Downpipes shown indicatively. Layout and flow rate TBC by Contractor.

2. Movement Joints in brick wall

TBC by Contractor. 3. Brick Support angle details by Structural Engineer.

G	14.04.21	Windows amended to aluminium	JJ	РВ
F	31.08.19	External boiler flue chimney removed from Block C	EK	
Е	26.07.18	Windows opening types added	AP	
D	23.07.18	MJs and rainwater pipes added	AP	
С	29.06.18	Levels and Brick support added	AP	
В	25.04.18	General Update	Bk	JJ
А	12.04.18	Planning Issue	ВК	JJ

Rev: Date: Details:





lpswich IP1 1LG

