

3 Princes Garden, Glasgow, G12 9HP



We are going to be replacing the existing casements in the bay with newly manufactured timber casement windows as the existing are rotting and have failed to insulate the property. Condensation builds up quite badly and over time this has affected the timber. The new casements will be fitted into the existing cases. We will also be replacing the existing sash and case with new top and bottom sashes fitted into the existing case. Newly manufactured windows will insulate the property more effectively and stop condensation building



Timbers are breaking at joints



Timbers are breaking at joints



This is typically how much condensation builds, there is water sitting on the timbers which will weaken timbers even more



Paint work is breaking away from timbers due to rot