



5816 Millais Hs. Ground Floor  
20 Apr 2021

Millbank Estate  
5816

Gunite  
United Living

ITEM  
1  
FLOOR  
Ground  
ROOM  
Elev A  
SHEET

**ISSUE**  
Install cemties or helibeam as per structural engineer instruction



**COMMENTS**  
Structural engineer required



ITEM  
2  
FLOOR  
Ground  
ROOM  
Elev A  
SHEET

**ISSUE**  
As bove


**COMMENTS**



ITEM  
3  
FLOOR  
Ground  
ROOM  
Elev A  
SHEET

**ISSUE**  
As above


**COMMENTS**



ITEM  
4  
FLOOR  
Ground  
ROOM  
Elev B  
SHEET

**ISSUE**  
1 brick to replace

**COMMENTS**





5816 Millais Hs. Ground Floor  
20 Apr 2021



Millbank Estate  
5816

Gunite  
United Living

ITEM  
5  
FLOOR  
Ground  
ROOM  
Elev B  
SHEET

ISSUE  
2 bricks to replace


COMMENTS



ITEM  
6  
FLOOR  
Ground  
ROOM  
Elev B  
SHEET

ISSUE  
2 helibars, 2 bricks to replace


COMMENTS



ITEM  
7  
FLOOR  
Ground  
ROOM  
Elev C  
SHEET

ISSUE  
1 brick to replace



COMMENTS



ITEM  
8  
FLOOR  
Ground  
ROOM  
Elev C  
SHEET

ISSUE  
0.25 sqm pointing

COMMENTS





5816 Millais Hs. Ground Floor  
20 Apr 2021


Millbank Estate  
5816

Gunite  
United Living

ITEM  
9  
FLOOR  
Ground  
ROOM  
Elev C  
SHEET

ISSUE  
1 brick to replace


COMMENTS



ITEM  
10  
FLOOR  
Ground  
ROOM  
Elev D  
SHEET

ISSUE  
1 brick to replace



COMMENTS



ITEM  
11  
FLOOR  
Ground  
ROOM  
Elev D  
SHEET

ISSUE  
1 brick to replace



COMMENTS



ITEM  
12  
FLOOR  
Ground  
ROOM  
Elev D  
SHEET

ISSUE  
1 brick to replace

COMMENTS





5816 Millais Hs. Ground Floor  
20 Apr 2021


Millbank Estate  
5816

Gunite  
United Living

ITEM  
13  
FLOOR  
Ground  
ROOM  
Elev D  
SHEET

ISSUE  
4 helibars, 5 bricks to replace



COMMENTS



ITEM  
14  
FLOOR  
Ground  
ROOM  
Elev E  
SHEET

ISSUE  
1 brick to replace



COMMENTS



ITEM  
15  
FLOOR  
Ground  
ROOM  
Elev E  
SHEET

ISSUE  
Install cementies or helibeam as per structural engineer instruction



COMMENTS  
Structural engineer required



ITEM  
16  
FLOOR  
Ground  
ROOM  
Elev E  
SHEET

ISSUE  
Install cementies or helibeam as per structural engineer instruction

COMMENTS  
Structural engineer required





5816 Millais Hs. Ground Floor  
20 Apr 2021

Millbank Estate  
5816

Gunite  
United Living

ITEM  
17  
FLOOR  
Ground  
ROOM  
Elev E  
SHEET

**ISSUE**  
Install cemties or helibeam as per structural engineer instruction


**COMMENTS**  
Structural engineer required



ITEM  
18  
FLOOR  
Ground  
ROOM  
Elev E  
SHEET

**ISSUE**  
Install cemties or helibeam as per structural engineer instruction

**COMMENTS**  
Structural engineer required



ITEM  
19  
FLOOR  
Ground  
ROOM  
Elev F  
SHEET

**ISSUE**  
Install cemties or helibeam as per structural engineer instruction


**COMMENTS**  
Structural engineer required



ITEM  
20  
FLOOR  
Ground  
ROOM  
Elev F  
SHEET

**ISSUE**  
2 bricks to replace

**COMMENTS**





5816 Millais Hs. Ground Floor  
20 Apr 2021

Millbank Estate  
5816

Gunite  
United Living

ITEM  
21  
FLOOR  
Ground  
ROOM  
Elev F  
SHEET

**ISSUE**  
Install cement ties or helibeam as per structural engineer instruction


**COMMENTS**  
Structural engineer required



ITEM  
22  
FLOOR  
Ground  
ROOM  
Elev B  
SHEET

**ISSUE**  
6 bricks

**COMMENTS**  
Existing brick repairs



ITEM  
23  
FLOOR  
Ground  
ROOM  
Elev B  
SHEET

**ISSUE**  
10 bricks

**COMMENTS**  
Existing brick repairs

