Riverside House, Woolwich

26 July 2021

Prepared for Shall Do Stoke Road Ltd





Prepared for:

Shall Do Stoke Road Ltd

Prepared by:

Markides Associates 81 Southwark Bridge Road London SE1 ONQ United Kingdom

T: +44 (0)20 7442 2225

E: info@markidesassociates.co.uk W: markidesassociates.co.uk

Project Number: 21206

Doc Number: 21206-MA-XX-XX-RP-D-FR01

Rev	Issue Purpose	Author	Checked	Reviewed	Approved	Date
	Final	DR	DM	DR	AKS	05.07.21
Α	Final	DR	DM	DR	AKS	20.07.21
В	Final	DR	DM	DR	AKS	26.07.21

Copyright 2021 Markides Associates Ltd. The concepts and information contained in this document are the property of Markides Associates. Use or copying of this document in whole or in part without the written permission of Markides Associates constitutes an infringement of copyright.

Limitation: This report has been prepared on behalf of, and for the exclusive use of the client of Markides Associates, and is subject to, and issued in accordance with, the provisions of the contract between the client and Markides Associates.

Markides Associates accepts no liability or responsibility whatsoever for, or in respect of, any use of, or reliance upon, this report by any third party.

Riverside House, Woolwich



# **Contents**

1.	INTRODU	JCTION	3
2.	BASELIN	E CONDITIONS	5
3.	FLOOD R	ISK ASSESSMENT	7
4.	CONCLU	SION	9
Tab	les		
Table	1.1	Site Characteristics	3
Figu	ires		
Figure	1.1	Site Location Plan	
Figure	2.1	British Geological Survey	
Figure	2.2	Anglian Water Sewer Record	
Figure	3.1	EA Flood map for planning	
Figure	3.2	EA Flood risk from surface water	
Figure	e 3.3	Groundwater Vulnerability Map	

# **Appendices**

Appendix A – Proposed Development Plans

Appendix B – Thames Water Records & Correspondence



#### 1. Introduction

1.1.1 Markides Associates (MA) has been instructed by Shall Do Stoke Road Ltd (the Applicant) to prepare a Flood Risk Assessment (FRA) in support of their development proposals for Riverside House.

#### 1.2 FRA Requirement & Scope

- 1.2.1 The Town and Country Planning (General Permitted Development) (England) Order 2015, which came into force on the 15th of April 2015, and its subsequent 2016 Amendment which came into force on the 6th April 2016, sets out the permitted development rights for the conversion of offices to residential development under Class O. Development of this nature (Class O) will consist of "a change of use of a building and any land within its curtilage from a use falling within Class B1(a) (offices) of the Schedule to the Use Classes Order, to a use falling within Class C3 (dwelling houses) of that Schedule."
- 1.2.2 The Order states that the local planning authority must also have regard to the National Planning Policy Framework (NPPF), so far as relevant to the subject matter of the prior approval. The order states that development consisting of a change of use of a building and any land within its curtilage is permitted, subject to the condition that before the beginning of the development, the Applicant will apply to the local planning authority for a determination as to whether the prior approval of the authority will be required, with one of the considerations being flooding risks on the site.
- 1.2.3 In the preparation of this FRA, all sources of flooding have been assessed which may affect the development proposals and the surrounding areas, in accordance with the requirements of the current national and local flood risk management policy.

#### 1.3 Site Details

1.3.1 The site is located in Woolwich, south of the A206, within the Royal Borough of Greenwich (RBG). Refer to **Table 1.1** below for site details and **Figure 1.1** for a site location plan.

**Table 1.1** Site Characteristics

Site Address	Beresford Street, London, SE18 6BU	
Grid reference	543475mE, 179195mN (TQ 43475 79195)	
General Topography	Generally flat	
Site Area	0.429 ha	
Existing Use	Vacant commercial building	
Boundaries	North	Woolwich High Street
	East	Beresford Street
	South	Bunton Street
	West	Callis Close







#### 1.4 Planning History

- 1.4.1 In January 2019, prior approval was granted for a permitted development scheme relating to the "change of use of the site from office (Class B1a) to Residential (Class C3) forming 199 residential units" (planning reference: 18/4120/PN2).
- 1.4.2 The delegated report confirmed that the site is located in Flood Zone 1, at low risk of flooding. The application was reviewed by the Environment Agency and the RGB Flood Risk Manager, with neither consultee raising an objection in regard to flood risk. Thames Water were also consulted and raised no objection with respect to waste water infrastructure capacity.

## 1.5 Development Proposals

1.5.1 The development proposals supported by this FRA are comprised of a change of use of the existing office floor space to residential (C3 land use), with the provision of 209no. residential units. Refer to Appendix A for the proposed development plans.



## 2. Baseline Conditions

# 2.1 Topography

2.1.1 Levels across the site are generally flat, falling east to west.

#### 2.2 Hydrology

2.2.1 The River Thames is approximately 120m north of the site.

## 2.3 Geology

2.3.1 Based on the British Geological Survey (BGS) online dataset the site appears to be underlain by Head (Clay, Silt, Sand, and Gravel) over Thanet Formation (Sand) bedrock. Refer to **Figure 2.1** below.




Figure 2.1 British Geological Survey

2.3.2 Based on Defra's MAGIC map application, the site is not located in a Groundwater Source Protection Zone.



# 2.4 Existing Drainage Infrastructure

2.4.1 Based on Thames Water sewer records, the site appears to be served by a number of private combined sewers. Based on the site's topography, the sewers will likely convey flows to the Thames Water 225mm dia. foul sewer in Bunton Street. Refer to **Figure 2.2** below for an extract of the map. The full search is included in **Appendix B**.

914x610

4201

A33

The Site

914x610

5284

725

Callis Yard

4101

4101


4102

Figure 2.2 Thames Water Sewer Record



3.1.1 Based on the EA Flood map for planning, the site appears to be located in Flood Zone 1, refer to **Figure 3.1** below.





3.1.2 Areas within Flood Zone 1 are considered to have a less than 1 in 1,000 year annual probability of flooding (0.1%). Therefore, the risk of tidal/fluvial flooding is assessed as low.

#### 3.2 Pluvial Flooding

3.2.1 Based on the EA long term flood risk information, the majority of the site appears to be at very low risk of surface water flooding, with a small area at medium risk of flooding. Refer to **Figure 3.2** below for the EA Flood risk from surface water map.

Figure 3.2 EA Flood risk from surface water



3.2.2 This risk will be managed by the existing drainage and gullies in this area. Therefore, the risk of surface water flooding is assessed as low.



#### 3.3 Groundwater Flooding

3.3.1 Based on Defra's MAGIC Map application, the site appears to have a Medium-High vulnerability to groundwater, based on the permeable sand bedrock. Refer to **Figure 3.3** below.

Beacon
Beacon
Beacon
Beacon
Beacon
Beacon
Terminal
Hard
Amb
Mud
Slipway
Beacon
The Site

The Site

Centre
Callis Yard

Dial
Square

Dial
Square

Dial
Square

PW

Medium - High
Medium - Low
Low
Unproductive

Circen's End

PW

Circen's End

PW

Circen's End

PW

Figure 3.3 Groundwater Vulnerability Map

3.3.2 The proposals are comprised primarily of internal modifications, with no significant groundworks. Therefore, the risk of groundwater flooding is assessed as low.

#### 3.4 Flooding from Sewers

- 3.4.1 Based on Thames Water's sewer flooding history records, there have been no incidents of flooding from sewer surcharge at the site. Refer to **Appendix B** for Thames Water sewer flooding history records.
- 3.4.2 Therefore, the risk of flooding from sewer surcharge is assessed as low.

#### 3.5 Artificial Sources

3.5.1 The site is not located in an area at risk of flooding from artificial sources. Therefore, the risk of flooding from reservoirs, lakes, and artificial sources is assessed as low.

## 3.6 Strategic Flood Risk Assessment

- 3.6.1 The Royal Borough of Greenwich has completed a Strategic Flood Risk Assessment (SFRA), dated October 2011.
- 3.6.2 Data within the SFRA confirms that the site is not located within a Critical Drainage Area (CDA).



#### 4. Conclusion

- 4.1.1 Markides Associates has been instructed to prepare a Flood Risk Assessment (FRA) in support of their development proposals for Riverside House, Beresford Street, Woolwich, SE18 6BU.
- 4.1.2 The development proposals are comprised of a change of use of the existing office floor space to provide 209no. residential units.
- 4.1.3 Based on the EA Flood map for planning, the site appears to be located in Flood Zone 1. Sites in Flood Zone 1 are considered to have a less than 1 in 1,000 year annual probability of flooding (0.1%). The flood risk from all other sources is assessed as low.
- 4.1.4 In conclusion, this report demonstrates that the proposals are consistent with the aims of the NPPF and the Local Flood Risk Management Strategy. The site can be developed without increasing the risk of flooding on site or elsewhere, and the proposed units will not be at an unacceptable risk of flooding from rivers, surface water, groundwater, sewers, or artificial sources.



# **APPENDIX A – PROPOSED DEVELOPMENT PLANS**




E-mail: admin@oselarch.co.uk Web: www.oselarchitecture.co.uk @copyright exists on the designs and information shown on this drawing

THE CONTRACTOR MUST VERIFY ALL DIMENSIONS ON SITE BEFORE MAKING SHOP DRAWINGS OR COMMENCING WORK OF ANY KIND. NO DIMENSIONS TO BE SCALED FROM THIS DRAWING.



# APPENDIX B – THAMES WATER RECORDS & CORRESPONDENCE





Riverside House, Woolwich



NB. Levels quoted in metres Ordnance Newlyn Datum. The value -9999.00 indicates that no survey information is available

Manhole Reference	Manhole Cover Level	Manhole Invert Level
3201	n/a	2.24
3215	6.86	4.56
32WW 42ZV	n/a n/a	n/a n/a
42ZW	n/a	n/a
31TY	n/a	n/a
31TW	n/a	n/a
31UV	n/a	n/a
31UU 31UT	nia nia	n/a n/a
3101	7.17	4.73
31YB	n/a	n/a
31TZ	n/a	n/a
31UQ 31WW	n/a n/a	n/a n/a
30WT	n/a	n/a
30WV	n/a	n/a
30WU	n/a	n/a
30WR 30WQ	n/a n/a	n/a
31XY	n/a	n/a n/a
31QX	n/a	n/a
4201	10.14	n/a
40TW	n/a	n/a
41YT 41YR	n/a n/a	n/a
41XV	n/a	nia nia
41YS	n/a	n/a
41XW	n/a	n/a
41XX	n/a 40.75	n/a
4101 51YR	10.76 n/a	7.53 n/a
5204	10.1	8.9
51YS	n/a	n/a
52YY	n/a	n/a
30VT 30YR	n/a n/a	n/a
30WX	n/a	n/a n/a
4007	9.85	7.14
40WS	n/a	n/a
30WW	n/a	n/a
30VZ 40WU	n/a n/a	n/a n/a
40WT	n/a	n/a
40TU	n/a	n/a
40WV	n/a	n/a
4006 40TX	10	7.46
40US	n/a n/a	n/a n/a
40TV	n/a	n/a
40UR	n/a	n/a
41ZQ	n/a	n/a
31QZ 41YZ	n/a n/a	n/a n/a
41YV	n/a	n/a
31UX	n/a	n/a
4103	n/a	n/a
31QV 31QW	n/a	n/a
31YE	n/a n/a	n/a n/a
4102	10.08	7.09
31ZA	n/a	n/a
31YF	n/a	n/a
41YX 31ID	n/a n/a	n/a n/a
41YY	n/a n/a	n/a
3104	8.3	5.45
41XR	n/a	n/a
41XQ 31YA	n/a	n/a
41YW	n/a n/a	nia nia
41XT	n/a	n/a
31QT	n/a	n/a
31QS 31QR	n/a	n/a
31VU	n/a n/a	n/a
31ZB	n/a n/a	n/a n/a
31VX	n/a	n/a
315Y	n/a	n/a
41XZ	n/a	n/a
3105	7.27	5.07
	7.27 n/a	n/a
3105 41XY 41YQ 32WV	7.27	
3105 41XY 41YQ	7.27 n/a n/a	n/a n/a

The position of the apparatus shown on this plan is given without obligation and warranty, and the accuracy cannot be guaranteed. Service pipes are not shown but their presence should be anticipated. No liability of any kind whatsoever is accepted by Thames Water for any error or omission. The actual position of mains and services must be verified and established on site before any works are undertaken.

# Sewer Flooding History Enquiry



Markides Associates

81 Southwark Bridge Road

Search address supplied Riverside House

Riverside House Beresford Street

London SE18 6BU

**Your reference** 21153 Riverside House

Our reference SFH/SFH Standard/2021\_4434160

Received date 21 May 2021

Search date 21 May 2021



Thames Water Utilities Ltd Property Searches, PO Box 3189, Slough SL1 4WW DX 151280 Slough 13



searches@thameswater.co.uk www.thameswater-propertysearches.co.uk



# Sewer Flooding History Enquiry



**Search address supplied:** Riverside House, Riverside House, Beresford Street, London, SE18 6BU

This search is recommended to check for any sewer flooding in a specific address or area

TWUL, trading as Property Searches, are responsible in respect of the following:-

- (i) any negligent or incorrect entry in the records searched;
- (ii) any negligent or incorrect interpretation of the records searched;
- (iii) and any negligent or incorrect recording of that interpretation in the search report
- (iv) compensation payments



Thames Water Utilities Ltd Property Searches, PO Box 3189, Slough SL1 4WW DX 151280 Slough 13



searches@thameswater.co.uk www.thameswater-propertysearches.co.uk



# **Sewer Flooding**

**History Enquiry** 



#### **History of Sewer Flooding**

Is the requested address or area at risk of flooding due to overloaded public sewers?

The flooding records held by Thames Water indicate that there have been no incidents of flooding in the requested area as a result of surcharging public sewers.

#### For your guidance:

- A sewer is "overloaded" when the flow from a storm is unable to pass through it due to a permanent problem (e.g. flat gradient, small diameter).
   Flooding as a result of temporary problems such as blockages, siltation, collapses and equipment or operational failures are excluded.
- "Internal flooding" from public sewers is defined as flooding, which enters
  a building or passes below a suspended floor. For reporting purposes,
  buildings are restricted to those normally occupied and used for
  residential, public, commercial, business or industrial purposes.
- "At Risk" properties are those that the water company is required to include in the Regulatory Register that is presented annually to the Director General of Water Services. These are defined as properties that have suffered, or are likely to suffer, internal flooding from public foul, combined or surface water sewers due to overloading of the sewerage system more frequently than the relevant reference period (either once or twice in ten years) as determined by the Company's reporting procedure.
- Flooding as a result of storm events proven to be exceptional and beyond the reference period of one in ten years are not included on the At Risk Register.
- Properties may be at risk of flooding but not included on the Register where flooding incidents have not been reported to the Company.
- Public Sewers are defined as those for which the Company holds statutory responsibility under the Water Industry Act 1991.
- It should be noted that flooding can occur from private sewers and drains which are not the responsibility of the Company. This report excludes flooding from private sewers and drains and the Company makes no comment upon this matter.
- For further information please contact Thames Water on Tel: 0800 316 9800 or website www.thameswater.co.uk



Thames Water Utilities Ltd Property Searches, PO Box 3189, Slough SL1 4WW DX 151280 Slough 13




searches@thameswater.co.uk www.thameswater-propertysearches.co.uk



0800 009 4540

#### Riverside House, Woolwich





Riverside House, Woolwich



NB. Levels quoted in metres Ordnance Newlyn Datum. The value -9999.00 indicates that no survey information is available

Manhole Reference	Manhole Cover Level	Manhole Invert Level
3201	n/a	2.24
3215	6.86	4.56
32WW	n/a	n/a
42ZV	n/a	n/a
42ZW 31TY	n/a n/a	n/a n/a
31TW	n/a	n/a
31UV	n/a	n/a
3100	n/a	n/a
31UT	n/a	n/a
3101	7.17	4.73
31YB	n/a	n/a
31TZ	n/a	n/a
31UQ 31WW	n/a n/a	n/a n/a
30WT	n/a	n/a
30WV	n/a	n/a
30WU	n/a	n/a
30WR	n/a	n/a
30WQ	n/a	n/a
31XY	n/a	n/a
31QX 4201	n/a 10.14	n/a n/a
40TW	n/a	n/a n/a
41YT	n/a	n/a
41YR	n/a	n/a
41XV	n/a	n/a
41YS	n/a	n/a
41XW	n/a	n/a
41XX 4101	n/a 10.76	n/a 7.53
51YR	10.76 n/a	7.53 n/a
5204	10.1	8.9
51YS	n/a	n/a
52YY	n/a	n/a
30VT	n/a	n/a
30YR	n/a	n/a
30WX 4007	n/a 0.95	n/a
4007 40WS	9.85 n/a	7.14 n/a
30WW	n/a n/a	n/a n/a
30VZ	n/a	n/a
40WU	n/a	n/a
40WT	n/a	n/a
40TU	n/a	n/a
40WV	n/a	n/a
4006 40TX	n/a	7.46
40US	n/a n/a	n/a n/a
40TV	n/a	n/a
40UR	n/a	n/a
41ZQ	n/a	n/a
31QZ	n/a	n/a
41YZ	n/a	n/a
31UX	n/a	n/a
4103	n/a n/a	n/a n/a
31QV	n/a	n/a
31QW	n/a	n/a
31YE	n/a	n/a
4102	10.08	7.09
31ZA	n/a	n/a
31YF 41YX	n/a	n/a
31ID	n/a n/a	n/a
41YY	n/a n/a	n/a n/a
3104	8.3	5.45
41XR	n/a	n/a
41XQ	n/a	n/a
31YA	n/a	n/a
41YW 41XT	n/a	n/a
31QT	n/a n/a	n/a
31QS	n/a	n/a n/a
31QR	n/a	n/a n/a
31VU	n/a	n/a
31ZB	n/a	n/a
31VX	n/a	n/a
315Y	n/a	n/a
41XZ 3105	n/a	n/a
41XY	7.27 n/a	5.07
41YQ	n/a n/a	n/a n/a
32WV	n/a	n/a
42ZU	n/a	n/a
The position of the apparatus shown on this plan	is given without obligation and warranty, and the ac-	curacy cannot be guaranteed. Service pipes are not

The position of the apparatus shown on this plan is given without obligation and warranty, and the accuracy cannot be guaranteed. Service pipes are not shown but their presence should be amicipated. No liability of any kind whatsoever is accepted by Thames Water for any error or omission. The actual position of mains and services must be verified and established on site before any works are undertaken.