

# GORDON SILVER JOINERY LTD

SILVER BIRCH, CAMMACHMORE AB39 3NR  
TELEPHONE – 0771 049 6697 REGISTRATION NUMBER – SC462612  
VAT REGISTRATION NUMBER – 977 8878 19

19<sup>th</sup> August 2019

Stonehaven Fetteresso Church of Scotland  
Bath Street  
Stonehaven  
AB39 2DH

For the attention of Mr. Dick Jenkins Property Convener

Dear Mr Jenkins,  
Fetteresso Church Hall North Windows


I confirm that I recently inspected the two vertical windows located on the north wall of the hall at Fetteresso Church. This is in response to your request for an expert opinion regarding the current condition of the windows.

The windows are constructed from wood. I can confirm that the structural integrity of the frames of both windows is now in such a condition that they are beyond repair. At some point the frames will be unable to sustain the weight of the glass and they will become a safety hazard. The root cause of this situation has been a failure to undertake maintenance in the form of an external paint program.

I can confirm that it would be possible to destruct the current windows from the inside of the hall. Subsequent to this, replacement frames could also be installed from the inside.

Please do not hesitate to contact me if you require any further assistance with this matter.

Yours sincerely,



Gordon Silver  
Joiner