



WINDOWS

- * HANDMADE REPLACEMENT WOODEN WINDOWS. 'LIKE FOR LIKE' TO MATCH EXISTING.
- NOTE! THESE REPLACEMENT WINDOWS AWAIT BAT ACTIVITY BEFORE FITTING.
- ALL OTHER WINDOWS TO HAVE SIMPLE REPAIRS AND REDECORATION.
- NEW BLACK UPVC SUP AND BRANCHES TO MATCH EXISTING.

[REFER TO HERITAGE IMPACT ASSESSMENT B.I.F.]

REV D 03.22

* NOTE: REFER TO HIGHWAY CONSULTANT DETAILS.

REVISION C 11.21
EXTERNAL WORKS TO COTTAGE ③ OMITTED.

REVISION B 05.21
UPDATED TO REFLECT EXTERNAL WORKS TO COTTAGES ①, ② + ③

REVISION A 03.21
EXTENT OF REPLACEMENT WINDOWS CLARIFIED.

REVISION D 03.22
SOIL AND RAINWATER DRAINAGE MATERIALS AND WINDOWS UPDATED.

07 PROPOSED ELEVATIONS 1:100

PROPOSED REINSTATEMENT WORKS TO CASTLE BUILDINGS
LLANRHAEDR - YM - MOCHNANT 02.21