

SIMON ARCHER

8 Trenavin Close Crediton EX17 2EZ

07966 347 957

simon@architectural-services.org Website architectural-services.org

Surface Water Strategy:

The surface water from the new extension could be directed to a soakaway. There is a large amount of land to contain a soakaway and this rainwater run-off will not cause flooding to any roads or property.