Visibility improved to oncoming traffic to 2.4 x 80m by rebuilding wall as road bends away towards the village.

Brick pier including capping to be rebuilt using lime mortar, same bond and details both sides of entrance.



Burnham Road.

Wall removed and rebuilt in matching external wall finishes of flintwork between brick quoins


Visibility improved to oncoming traffic to 2.4 x 80m by rebuilding wall as road bends away towards the village.

16850


Front Entrance Access Plan Showing Visibility Improvements 1:50

East Elevation Through Access looking towards village I:50 As Proposed

Burnham Road .



centre line



IAN · H · BIX Associates Ltd M·C· I· A· T ARCHITECTURAL AND BUILDING CONSULTANTS SANDPIPER HOUSE, LEETE WAY, WEST WINCH KING'S LYNN, NORFOLK PE33 OST TEL: 01553 844077 FAX: 01553 844078 EMAIL: mail@ianbix.co.uk WEB: www.ianbix.co.uk

Road Front Garden Wall
Manor House
Burnham Road
South Creake

Road Frontage
Garden Wall
Proposed Entrance
Alterations to Improve
Visibility

1:50 @ A1

Date September 2022

Drawn JAF / IHB

Drawing No. 2486-25A

Ian. H. Bix Member Chartered Institute of Architectural Technologists