

DRAWING TITLE
HOUSE - EXISTING & PROPOSED REAR ELEVATION

PROJECT NAME Double Glazed Windows

SITE ADDRESS
 Rectory Farmhouse, 39 Toghill Lane, Doynton, South Glos, BS30 5SY

CLIENT C Asprey / R Greenwood

| DATE | REV | ISSUED BY | TO | REMARK |
|----------|-----|-----------|----|----------------|
| 04-11-21 | 1 | DR | CA | Planning & LBC |
| 10-05-23 | 2 | JHC | CA | Planning & LBC |

nash partnership

Bath : 01225 442424 | 23a Sydney Buildings, Bath, BA2 6BZ
 Bristol : 0117 3327560 | The Generator, Counterslip, Redcliffe, Bristol, BS1 6BX

www.nashpartnership.com
 mail@nashpartnership.com

NOTES / REMARKS

Summary
 Generally where original window openings remain, the window units are highly likely to be non original. Single glazed units causing ongoing harm within the interior of the building. Character deviated from likely original condition. Refer to other documents submitted as part of this application.



- W-17**
 -Original window opening
 -Original stone Mullions
 -Non original single glazed plate glass.
 -Non original single glazed (timber) casement.
- W-18**
 -Original window opening
 -Original stone Mullions
 -Non original single glazed plate glass.
 -Non original single glazed (timber) casement.
- W-19**
 -Original window opening
 -Original stone Mullions
 -Non original single glazed plate glass.
 -Non original single glazed (timber) casement.
- W-20**
 -Original window opening
 -Original stone Mullions
 -Non original single glazed plate glass.
- W-21**
 -Non original window opening
 -Non original steel lintel
 -Non original double glazed (timber) casement
- W-22**
 -Non original window opening to extension
 -Non original oak frame
 -Non original double glazed plate glass
- W-23**
 -Non original window opening
 -Non original steel lintel
 -Non original double glazed (timber) casement
- W-24**
 -Non original window opening
 -Non original concrete lintel
 -Non original double glazed (timber) casement
- W-25**
 -Non original window opening
 -Non original concrete lintel
 -Non original double glazed (timber) casement

01 - EXISTING (REAR) ELEVATION (FACING NORTH EAST)



- W-17**
 -Original window opening
 -Original stone Mullions
 -Proposed slimline glazing double glazed metal casement - see general window detail
- W-18**
 -Original window opening
 -Original stone Mullions
 -Proposed slimline glazing double glazed metal casement - see general window detail
- W-19**
 -Original window opening
 -Original stone Mullions
 -Proposed slimline glazing double glazed metal casement - see general window detail
- W-20**
 -Original window opening
 -Original stone Mullions
 -Proposed slimline glazing double glazed metal casement - see general window detail
- W-21**
 -Non original window opening
 -Non original steel lintel
 -Non original double glazed (timber) casement
- W-22**
 -Non original window opening to extension
 -Non original oak frame
 -Non original double glazed plate glass
- W-23**
 -Non original window opening
 -Non original steel lintel
 -Non original double glazed (timber) casement
- W-24**
 -Non original window opening
 -Non original concrete lintel
 -Non original double glazed (timber) casement
- W-25**
 -Non original window opening
 -Non original concrete lintel
 -Non original double glazed (timber) casement

01 - PROPOSED (REAR) ELEVATION (FACING NORTH EAST)



Responsibility is not accepted for errors made by others in scaling from this drawing. All dimensions must be checked on site. All construction information should be taken from figured dimensions only. Any discrepancies or uncertainties must be reported to the Architect before proceeding. The purpose of this drawing is clearly stated. To be read along side any specifications or other information. © Nash Partnership 2023