

ARCHITECTURAL SERVICES

RICHARD & SIMON ARCHER Est 1987



SIMON ARCHER

8 Trenavin Close
Credon
EX17 2EZ

07966 347 957

simon@architectural-services.org
Website architectural-services.org

Surface Water Strategy:

There will be no change in the amount of rainwater run-off for the existing building, as no additional roof area is being created. The existing downpipes and rainwater is directed to a soakaway. There is a large amount of land to contain a soakaway and this rainwater run-off will not cause flooding to any roads or property.