

## Notes

 Copyright Jessop and Cook Architects Limited.
 Do not scale from drawings, all dimensions to be checked on site.

3. For more information on the condition of the fabric of the Barn and Stables please refer to the report produced by Hall & Ensom Chartered Surveyors "Building Condition Survey in respect of Lords Farm Barn" (August 2019).

KEY
Demolition of walls, partitions and other structures
— — Boundaries

 new conservation style rooflight
 stonesfield slated roof to be repaired and recovered. Slates required to be replaced to match existing

 new mock cast iron guttering along eave

existing course rubblestone wallnew mock cast iron rainwater

 Existing cement-based repairs
 to be remove and existing coursed rubblestone wall to be repointed using lime mortar to match existing

 New double glazed timber window to match existing window style. Existing window to be removed

A 22.10.2020 Added access slates for bats and AB bird boxes

## PLANNING ISSUE

Revisions

Conversion of thrashing barn into residence at Lords Farm, 2 Queen Street Eynsham, Witney OX29 4HQ

Oxford Preservation Trust 10 Turn Again Lane, St Ebbes, Oxford. OX1 1QL Drawing title

Proposed Sections A to D

JESSOP & COOK ARCHITECTS       WEST WING, SECOND FLOOR 9 PARK END STREET OXFORD OX1 1HH         T:01865 591212 E: info@jessopandcook.co.uk www.jessopandcook.co.uk         Scale at A1       Date       Drawn by       Checked         1:50       Sep 19       AB	ARCHITECTS Scale at A1 Date		Revision A		
9 PARK END STREET OXFORD OX1 1HH JESSOP & COOK ARCHITECTS T:01865 591212 E: info@jessopandcook.co.uk					Checked
9 PARK END STREET			E: info@jes	sopandcook.co.uk	
			9 PARK END	STREET	