

The Old Church, Mockbeggar Lane, Ibsley

Roof Repairs

HERITAGE STATEMENT

- *Please refer to full heritage report in the associated planning and listed building applications for a full assessment of the building*
- Repairs to the building are essential to ensure the timber roof does not rot further and fail/collapse. Fixing the roof will ensure the rest of the building survives as it should
- Existing roof is clay tile. Proposed roof covering will match the original roof material and colour, so no change the appearance or style of the building
- Tiles to be approved by the Conservation Officer
- Existing row of stone flag roof tiles to the front (north) elevation are being retained and re-fixed in their previous position – the last course of tiles above the gutter