### Heritage Statement for: - Hazelbury House, New Street, Painswick, Stroud, GL6 6UN

# Offical list entry

Heritage Category: Listed Building

Grade: II

List Entry Number: 1090986 Date first listed: 21-Oct-1955

List Entry Name: **HAZELBURY HOUSE** 

Statutory Address 1: HAZELBURY HOUSE, NEW STREET

Location

Statutory Address: **HAZELBURY HOUSE, NEW STREET** 

The building or site itself may lie within the boundary of more than one authority.

County: Gloucestershire

District: Stroud (District Authority)

Parish: Painswick

National Grid Reference: SO 86581 09672

#### Details

PAINSWICK NEW STREET SO 8609-8709 (Part) (north west side) 8/170 Hazelbury House 21.10.55 GV II Large house at end of row. Early C18. Limestone ashlar, concrete tile roof. Two storeys and attic, seven windows. A fine symmetrical frontage with continuous moulded string course at first floor, and a deep coved cornice above a continuous bead mould; centre and gable stacks all with moulded cappings. Central lonic gabled portico, covering 4-panel part glazed door with good early C19 decorative fanlight, flanked each side by 2 blank window recesses and a triple sash; at first floor are seven 4-pane sashes, and 4 segmental-headed 2-light casement dormers to roof. A deep wing runs back, left, indoors a long narrow round-headed stair window, and a cross-gabled unit with moulded strings at ground and first floor. Interior not inspected.

Listing NGR: SO8658109672

### Legacy

The contents of this record have been generated from a legacy data system.

Legacy System number: 133355

Legacy System: LBS

## Legal

This building is listed under the Planning (Listed Buildings and Conservation Areas) Act 1990 as amended for its special architectural or historic interest.

#### **Planned Work**

None of the planned work in the Listed Building Application S.23/2158/LBC will in any way affect the listing of the property as described above. The planned work is proposed to sympathetically replace (like for like) the rotten timber window 'only' and will not affect the dormer itself, nor the

roof construction in any way. This will not only restore the outward appearance of the property but will also restore the security and weather proofness of the property in the area requiring the restoration work.