

PHOTOGRAPHIC SCHEDULE



Photograph No 1

South facing elevation of the Bodley and Garner gate viewed from the high street.




Photograph No 2

North facing elevation of the Bodley and Garner gate viewed from St Johns Quad.

Photograph No 3

Modified photograph showing impression of proposed ironmongery arrangement.



Hasp folded back and fixed in place.

Pivoting Brace rotated 90 degrees and fixed in place retaining the existing ironmongery.

Boss installed to rear of brace back plate with notch to receive proposed slide arm.

New slide arm produced in materials to match existing ironmongery with new padlock ring and cast iron rosette knob.

Existing brackets relocated. 'Chock' to be installed with aperture to suit and secure new slide arm.

Existing 'shoot bolt' to be retained and extended in length using materials to match existing improving use. Later addition Hasp to be removed.



Photograph No 4

Existing 'Shoot bolt' retained and extended. Later addition hasp arrangement to be removed.



Photograph No 5

Existing Hasp retained. Hasp to be folded back and fixed in place on pivoting brace.



Photograph No 6

Existing bracket retained and relocated.
'Chock' to be installed within bracket with
aperture to receive new slide bolt.



Photograph No 7

Existing handle retained.



Photograph No 8

Existing Pivoting Brace retained. Brace to be turned 90 degrees and fixed in place. Boss to be installed behind back place with notch to receive proposed slide arm.



Photograph No 9

Existing bracket retained and relocated. 'Chock' to be installed within bracket with aperture to receive new slide bolt.

Refer to the Heritage Statement for further photographs and descriptions.