Address: Development Management

Cheshire West and Chester Council, 4 Civic Way, Ellesmere Port, CH65 OBE

0300 123 7027

Tel:

Email: planning@cheshirewestandchester.gov.uk **Web:** www.cheshirewestandchester.gov.uk



Householder Application for Planning Permission for works or extension to a dwelling; Listed Building Consent for alterations, extension or demolition of a listed building

Town and Country Planning Act 1990 (as amended); Planning (Listed Buildings and Conservation Areas Act) 1990 (as amended)

Publication of applications on planning authority websites

Please note that the information provided on this application form and in supporting documents may be published on the Authority's website. If you require any further clarification, please contact the Authority's planning department.

Site Location				
Disclaimer: We can only make recommendations based on the answers given in the questions.				
If you cannot provide a postcode, the description of site location must be completed. Please provide the most accurate site description you can, to help locate the site - for example "field to the North of the Post Office".				
Number	1			
Suffix				
Property Name				
Address Line 1				
Grosvenor Place				
Address Line 2				
Address Line 3				
Cheshire West And Chester				
Town/city				
Chester				
Postcode				
CH1 2DE				
Description of site location must				
Easting (x)		Northing (y)		
340516		366002		

Applicant Details Name/Company Title Mrs First name Charlotte Surname Jobse Company Name	
Name/Company Title Mrs First name Charlotte Surname Jobse	
Name/Company Title Mrs First name Charlotte Surname Jobse	
Title Mrs First name Charlotte Surname Jobse	
Mrs First name Charlotte Surname Jobse	
First name Charlotte Surname Jobse	
Charlotte Surname Jobse	
Surname Jobse	
Jobse	
Company Name	
Address	
Address line 1	
43 VINCENT DRIVE	
Address line 2	
Address line 3	
Town/City	
Chester	
County	
Country	
United Kingdom	
Postcode	
CH4 7RQ	
Are you an agent esting an habelf of the applicant?	
Are you an agent acting on behalf of the applicant? O Yes	
⊙ No	

Description

Picca younder REDACTED **** Secondary number Email address *** *** *** ** ** ** ** **	Contact Details
Enall address Email address Description of Proposed Works Please describe the proposed works The repair of the small, single story, concrete tile extension roof of the house we purchased in July this year at 1, Grosvenor Place, Chester, Cht 120E. The dilapidated roof is leaking water into the property and into the supporting walls causing major water and damp issues. The roofers all state that the roof is leaking for several reasons. The pitch/angle of the roof (9-10*) is too low for proper water drainage, the roof has no eaves (not coming over the gables/supporting walls), many broken tiles and the condition of the roof in general. To repair the roof according to current building regulations the roofers work will replace the concrete roof with slate tiles, create small eaves and slightly raise the current roof pitch from 10* to 15-20* to achieve the absolute minimum required argie for slate. New concrete tiles would require a higher pitch which we do not preter. We would also opt for (Welsh) slate as this will be in keeping with the main roof of the property and surrounding properties. Unfortunately we find ourselves in a rather urgent situation as it needs repair as soon as possible to stop further water damage especially with the winter season ahead. The problems with the roof were initially identified by the ISVA home surveyor during the purchase of the property in June this year. We can provide the report if needed. Listed Building Grading What is the grading of the listed building (as stated in the list of Buildings of Special Architectural or Historical Interest? Orata in Carda in Carda in the grading of the listed building? Obort know Orata in the cardinal state that the cardinal properties.	Primary number
Email address	***** REDACTED *****
Email address Please describe the proposed Works Please describe the proposed works The repair of the small, single story, concrete tile extension roof of the house we purchased in July this year at 1, Grosvenor Place, Chester, CH1 2DE. The dilapidated roof is leaking water into the property and into the supporting walls causing major water and damp issues. The roofers all state that the roof is leaking for several reasons: The pitch/angle of the roof (9-10') is too low for proper water drainage, the roof has no eaves (not coming over the gables/supporting walls), many broken tiles and the condition of the roof in general. To repair the roof according to current building regulations the roofers work will replace the condition of the roof in general. To repair the roof according to current of 10' to 15-20' to achieve the absolute minimum required angle for slate. New concrete tiles would require a higher pitch which we do not prefer. We would also got for (Weish) slate as this will be in keeping with the main roof of the property and surrounding properties. Unfortunately ee find ourselves in a rather urgent situation as it needs repair as soon as possible to stop further water damage especially with the winter season ahead. The problems with the roof were initially identified by the ISVA home surveyor during the purchase of the property in June this year. We can provide the report if needed. Yes No No Listed Building Grading What is the grading of the listed building (as stated in the list of Buildings of Special Architectural or Historical Interest)? Opon't know Grade II Grade II Grade II Grade II Opon't know Yes	Secondary number
Email address Please describe the proposed Works Please describe the proposed works The repair of the small, single story, concrete tile extension roof of the house we purchased in July this year at 1, Grosvenor Place, Chester, CH1 2DE. The dilapidated roof is leaking water into the property and into the supporting walls causing major water and damp issues. The roofers all state that the roof is leaking for several reasons: The pitch/angle of the roof (9-10') is too low for proper water drainage, the roof has no eaves (not coming over the gables/supporting walls), many broken tiles and the condition of the roof in general. To repair the roof according to current building regulations the roofers work will replace the condition of the roof in general. To repair the roof according to rurent not 0' to 15-20' to achieve the absolute minimum required angle for slate. New concrete tiles would require a higher pitch which we do not prefer. We would also got for (Welsh) slate as this will be in keeping with the main roof of the property and surrounding properties. Unfortunately we find ourselves in a rather urgent situation as it needs repair as soon as possible to stop further water damage especially with the winter season ahead. The problems with the roof were initially identified by the ISVA home surveyor during the purchase of the property in June this year. We can provide the report if needed. No State S	
Description of Proposed Works Please describe the proposed works The repair of the small, single story, concrete tile extension roof of the house we purchased in July this year at 1, Grosvenor Place, Chester, CH1 2DE. The dilapidated roof is leaking water into the property and into the supporting walls causing major water and damp issues. The roofers all state that the roof is leaking for several reasons: The pitch/angle of the roof (9-10°) is too low for proper water drainage, the roof has no eaves (not coming over the gables/supporting walls), many broken tiles and the condition of the roof in general. To repair the roof according to current building regulations the roofers work will replace the concrete roof with slate tiles, create small eaves and slightly raise the current roof pitch from 10° to 15-20° to achieve the absolute minimum required angle for slate. New concrete tiles would require a higher pitch which we do not prefer. We would also opt for (Welsh) slate as this will be in keeping with the main roof of the property and surrounding properties. Unfortunately we find ourselves in a rather urgent situation as it needs repair as soon as possible to stop further water damage especially with the winter season shead. The problems with the roof were initially identified by the ISVA home surveyor during the purchase of the property in June this year. We can provide the report if needed. Listed Building Grading What is the grading of the listed building (as stated in the list of Buildings of Special Architectural or Historical Interest)? Obon't know Grade II Grade II Grade II Grade III Grade III Grade III For the property and interest and the property and into the surveyor during the purchase of the property in June this year. We can provide the report if needed.	Fax number
Description of Proposed Works Please describe the proposed works The repair of the small, single story, concrete tile extension roof of the house we purchased in July this year at 1, Grosvenor Place, Chester, CH1 2DE. The dilapidated roof is leaking water into the property and into the supporting walls causing major water and damp issues. The roofers all state that the roof is leaking for several reasons: The pitch/angle of the roof (9-10°) is too low for proper water drainage, the roof has no eaves (not coming over the gables/supporting walls), many broken tiles and the condition of the roof in general. To repair the roof according to current building regulations the roofers work will replace the concrete roof with slate tiles, create small eaves and slightly raise the current roof pitch from 10° to 15-20° to achieve the absolute minimum required angle for slate. New concrete tiles would require a higher pitch which we do not prefer. We would also opt for (Welsh) slate as this will be in keeping with the main roof of the property and surrounding properties. Unfortunately we find ourselves in a rather urgent situation as it needs repair as soon as possible to stop further water damage especially with the winter season shead. The problems with the roof were initially identified by the ISVA home surveyor during the purchase of the property in June this year. We can provide the report if needed. Listed Building Grading What is the grading of the listed building (as stated in the list of Buildings of Special Architectural or Historical Interest)? Obon't know Grade II Grade II Grade II Grade III Grade III Grade III For the property and damage and the condition of the property and into the property and the property and the roof were initially identified by the ISVA home surveyor during the purchase of the property in June this year. We can provide the report if needed.	
Description of Proposed Works Please describe the proposed works The repair of the small, single story, concrete tile extension roof of the house we purchased in July this year at 1, Grosvenor Place, Chester, CH1 2DE. The dilapidated roof is leaking water into the property and into the supporting walls causing major water and damp issues. The roofers all state that the roof is leaking for several reasons: The pitch/angle of the roof (9-10°) is too low for proper water drainage, the roof has no eaves (not coming over the gables/supporting walls), many broken tiles and the condition of the roof in general. To repair the roof according to current building regulations the roofers work will replace the concrete roof with slate tiles, create small eaves and slightly raise the current roof pitch from 10° to 15-20° to achieve the absolute minimum required angle for slate. New concrete tiles would require a higher pitch which we do not prefer. We would also opt for (Welsh) slate as this will be in keeping with the main roof of the property and surrounding properties. Unfortunately we find ourselves in a rather urgent situation as it needs repair as soon as possible to stop further water damage especially with the winter season ahead. The problems with the roof were initially identified by the ISVA home surveyor during the purchase of the property in June this year. We can provide the report if needed. Listed Building Grading What is the grading of the listed building (as stated in the list of Buildings of Special Architectural or Historical Interest)? O pon't know O Grade I Grade II Grade II Is it an ecclesiastical building? Don't know O'ves	Email address
Please describe the proposed works The repair of the small, single story, concrete tile extension roof of the house we purchased in July this year at 1, Grosvenor Place, Chester, CH1 2DE. The dilapidated roof is leaking water into the property and into the supporting walls causing major water and damp issues. The roofers all state that the roof is leaking for several reasons: The pitch/angle of the roof (9-10') is too low for proper water drainage, the roof has no eaves (not coming over the gables/supporting walls), many broken tiles and the condition of the roof in general. To repair the roof according to current building regulations the roofers work will replace the concrete roof with slate tiles, create small eaves and slightly raise the current roof pitch from 10' to 15-20' to achieve the absolute minimum required angle for slate. New concrete tiles would require a higher pitch which we do not prefer. We would also opt for (Welsh) slate as this will be in keeping with the main roof of the property and surrounding properties. Unfortunately we find ourselves in a rather urgent situation as it needs repair as soon as possible to stop further water damage especially with the winter season ahead. The problems with the roof were initially identified by the ISVA home surveyor during the purchase of the property in June this year. We can provide the report if needed. Has the work already been started without consent? Yes No No Listed Building Grading What is the grading of the listed building (as stated in the list of Buildings of Special Architectural or Historical Interest)? Onon't know Grade II Grade II Grade II Is it an ecclesiastical building? Onon't know Onon't know Onon't know	**** REDACTED *****
Please describe the proposed works The repair of the small, single story, concrete tile extension roof of the house we purchased in July this year at 1, Grosvenor Place, Chester, CH1 2DE. The dilapidated roof is leaking water into the property and into the supporting walls causing major water and damp issues. The roofers all state that the roof is leaking for several reasons: The pitch/angle of the roof (9-10') is too low for proper water drainage, the roof has no eaves (not coming over the gables/supporting walls), many broken tiles and the condition of the roof in general. To repair the roof according to current building regulations the roofers work will replace the concrete roof with slate tiles, create small eaves and slightly raise the current roof pitch from 10' to 15-20' to achieve the absolute minimum required angle for slate. New concrete tiles would require a higher pitch which we do not prefer. We would also opt for (Welsh) slate as this will be in keeping with the main roof of the property and surrounding properties. Unfortunately we find ourselves in a rather urgent situation as it needs repair as soon as possible to stop further water damage especially with the winter season ahead. The problems with the roof were initially identified by the ISVA home surveyor during the purchase of the property in June this year. We can provide the report if needed. Has the work already been started without consent? Yes No No Listed Building Grading What is the grading of the listed building (as stated in the list of Buildings of Special Architectural or Historical Interest)? Onon't know Grade II Grade II Grade II Is it an ecclesiastical building? Onon't know Onon't know Onon't know	
Please describe the proposed works The repair of the small, single story, concrete tile extension roof of the house we purchased in July this year at 1, Grosvenor Place, Chester, CH1 2DE. The dilapidated roof is leaking water into the property and into the supporting walls causing major water and damp issues. The roofers all state that the roof is leaking for several reasons: The pitch/angle of the roof (9-10') is too low for proper water drainage, the roof has no eaves (not coming over the gables/supporting walls), many broken tiles and the condition of the roof in general. To repair the roof according to current building regulations the roofers work will replace the concrete roof with slate tiles, create small eaves and slightly raise the current roof pitch from 10' to 15-20' to achieve the absolute minimum required angle for slate. New concrete tiles would require a higher pitch which we do not prefer. We would also opt for (Welsh) slate as this will be in keeping with the main roof of the property and surrounding properties. Unfortunately we find ourselves in a rather urgent situation as it needs repair as soon as possible to stop further water damage especially with the winter season ahead. The problems with the roof were initially identified by the ISVA home surveyor during the purchase of the property in June this year. We can provide the report if needed. Has the work already been started without consent? Yes No Don't know Grade I Grade II Grade II is it an ecclesiastical building? Ont know Or home surveyor during the purchase of the property in June this year. We can provide the report if needed.	Description of Proposed Works
CH1 2DE. The dilapidated roof is leaking water into the property and into the supporting walls causing major water and damp issues. The roofers all state that the roof is leaking for several reasons: The pitch/angle of the roof (9-10') is too low for proper water drainage, the roof has no eaves (not coming over the gables/supporting walls), many broken tiles and the condition of the roof in general. To repair the roof according to current building regulations the roofers work will replace the concrete roof with slate tiles, create small eaves and slightly raise the current roof pitch from 10' to 15-20' to achieve the absolute minimum required angle for slate. New concrete tiles would require a higher pitch which we do not prefer. We would also opt for (Welsh) slate as this will be in keeping with the main roof of the property and surrounding properties. Unfortunately we find ourselves in a rather urgent situation as it needs repair as soon as possible to stop further water damage especially with the winter season ahead. The problems with the roof were initially identified by the ISVA home surveyor during the purchase of the property in June this year. We can provide the report if needed. Has the work already been started without consent? Yes No Don't know Grade I Grade II Is it an ecclesiastical building? O Don't know Yes	Please describe the proposed works
roof has no eaves (not coming over the gables/supporting walls), many broken tiles and the condition of the roof in general. To repair the roof according to current building regulations the roofers work will replace the concrete roof with slate tiles, create small eaves and slightly raise the current roof pitch from 10° to 15-20° to achieve the absolute minimum required angle for slate. New concrete tiles would require a higher pitch which we do not prefer. We would also opt for (Welsh) slate as this will be in keeping with the main roof of the property and surrounding properties. Unfortunately we find ourselves in a rather urgent situation as it needs repair as soon as possible to stop further water damage especially with the winter season ahead. The problems with the roof were initially identified by the ISVA home surveyor during the purchase of the property in June this year. We can provide the report if needed. Has the work already been started without consent? Yes No No Listed Building Grading What is the grading of the listed building (as stated in the list of Buildings of Special Architectural or Historical Interest)? Onn't know Grade I Grade II Is it an ecclesiastical building? Don't know Yes	
and slightly raise the current roof pitch from 10" to 15-20" to achieve the absolute minimum required angle for slate. New concrete tiles would require a higher pitch which we do not prefer. We would also opt for (Welsh) slate as this will be in keeping with the main roof of the property and surrounding properties. Unfortunately we find ourselves in a rather urgent situation as it needs repair as soon as possible to stop further water damage especially with the winter season ahead. The problems with the roof were initially identified by the ISVA home surveyor during the purchase of the property in June this year. We can provide the report if needed. Has the work already been started without consent? ○ Yes ② No Listed Building Grading What is the grading of the listed building (as stated in the list of Buildings of Special Architectural or Historical Interest)? ○ Don't know ○ Grade I ⑤ Grade II Is it an ecclesiastical building? ○ Don't know ○ Yes	
○ Yes ○ No Listed Building Grading What is the grading of the listed building (as stated in the list of Buildings of Special Architectural or Historical Interest)? ○ Don't know ○ Grade I ○ Grade II* ○ Grade II Is it an ecclesiastical building? ○ Don't know ○ Yes	and slightly raise the current roof pitch from 10' to 15-20' to achieve the absolute minimum required angle for slate. New concrete tiles would require a higher pitch which we do not prefer. We would also opt for (Welsh) slate as this will be in keeping with the main roof of the property and surrounding properties. Unfortunately we find ourselves in a rather urgent situation as it needs repair as soon as possible to stop further water damage especially with the winter season ahead. The problems with the roof were initially identified by the ISVA home surveyor during the purchase of the property in June this year. We can
	Has the work already been started without consent?
What is the grading of the listed building (as stated in the list of Buildings of Special Architectural or Historical Interest)? O Don't know O Grade I O Grade II* O Grade II Is it an ecclesiastical building? O Don't know O Yes	
 ○ Don't know ○ Grade I ○ Grade II* ○ Grade II Is it an ecclesiastical building? ○ Don't know ○ Yes 	Listed Building Grading
○ Don't know ○ Yes	○ Don't know○ Grade I○ Grade II*
	○ Don't know ○ Yes
	⊗ No

Has a Certificate of Immunity from Listing been sought in respect of this building? ○ Yes ○ No
Demolition of Listed Building
Does the proposal include the partial or total demolition of a listed building? ○ Yes ⊙ No
Listed Building Alterations
Do the proposed works include alterations to a listed building? ☑ Yes ☑ No
Materials
Does the proposed development require any materials to be used?
Please provide a description of existing and proposed materials and finishes to be used (including type, colour and name for each material) demolition excluded
Type: Roof covering
Existing materials and finishes: concrete tiles not matching the slate tiles on the main house roof
Proposed materials and finishes: Slate tiles in keeping with the main roof and period of the property
Are you supplying additional information on submitted plans, drawings or a design and access statement? ✓ Yes ◯ No
If Yes, please state references for the plans, drawings and/or design and access statement
Quote and photos
Pedestrian and Vehicle Access, Roads and Rights of Way Is a new or altered vehicle access proposed to or from the public highway? Yes No

Is a new or altered pedestrian access proposed to or from the public highway? (Yes
⊙ No
Do the proposals require any diversions, extinguishment and/or creation of public rights of way? O Yes
⊙ No
Parking
Will the proposed works affect existing car parking arrangements?
○ Yes⊙ No
Trees and Hedges
Are there any trees or hedges on the property or on adjoining properties which are within falling distance of the proposed development?
Will any trees or hedges need to be removed or pruned in order to carry out your proposal?
○ Yes⊙ No
014 - 117 - 14
Site Visit Can the site be seen from a public road, public footpath, bridleway or other public land?
Site Visit Can the site be seen from a public road, public footpath, bridleway or other public land? ○ Yes ⊙ No
Can the site be seen from a public road, public footpath, bridleway or other public land? O Yes
Can the site be seen from a public road, public footpath, bridleway or other public land? ○ Yes ○ No If the planning authority needs to make an appointment to carry out a site visit, whom should they contact? ○ The agent
Can the site be seen from a public road, public footpath, bridleway or other public land? ○ Yes ○ No If the planning authority needs to make an appointment to carry out a site visit, whom should they contact?
Can the site be seen from a public road, public footpath, bridleway or other public land? ○ Yes ○ No If the planning authority needs to make an appointment to carry out a site visit, whom should they contact? ○ The agent ⊙ The applicant
Can the site be seen from a public road, public footpath, bridleway or other public land? ○ Yes ○ No If the planning authority needs to make an appointment to carry out a site visit, whom should they contact? ○ The agent ⊙ The applicant
Can the site be seen from a public road, public footpath, bridleway or other public land? Yes No If the planning authority needs to make an appointment to carry out a site visit, whom should they contact? The agent The applicant Other person Pre-application Advice Has assistance or prior advice been sought from the local authority about this application?
Can the site be seen from a public road, public footpath, bridleway or other public land? Yes No If the planning authority needs to make an appointment to carry out a site visit, whom should they contact? The agent The applicant Other person
Can the site be seen from a public road, public footpath, bridleway or other public land? Yes No If the planning authority needs to make an appointment to carry out a site visit, whom should they contact? The agent The applicant Other person Pre-application Advice Has assistance or prior advice been sought from the local authority about this application? Yes
Can the site be seen from a public road, public footpath, bridleway or other public land? Yes No If the planning authority needs to make an appointment to carry out a site visit, whom should they contact? The agent The applicant Other person Pre-application Advice Has assistance or prior advice been sought from the local authority about this application? Yes No If Yes, please complete the following information about the advice you were given (this will help the authority to deal with this application)
Can the site be seen from a public road, public footpath, bridleway or other public land? Yes No If the planning authority needs to make an appointment to carry out a site visit, whom should they contact? The agent The applicant Other person Pre-application Advice Has assistance or prior advice been sought from the local authority about this application? Yes No If Yes, please complete the following information about the advice you were given (this will help the authority to deal with this application more efficiently): Officer name: Title
Can the site be seen from a public road, public footpath, bridleway or other public land? Yes No If the planning authority needs to make an appointment to carry out a site visit, whom should they contact? The agent The applicant Other person Pre-application Advice Has assistance or prior advice been sought from the local authority about this application? Yes No If Yes, please complete the following information about the advice you were given (this will help the authority to deal with this application more efficiently): Officer name: Title
Can the site be seen from a public road, public footpath, bridleway or other public land? Yes No If the planning authority needs to make an appointment to carry out a site visit, whom should they contact? The agent The applicant Other person Pre-application Advice Has assistance or prior advice been sought from the local authority about this application? Yes No If Yes, please complete the following information about the advice you were given (this will help the authority to deal with this application more efficiently): Officer name: Title

Surname
***** REDACTED *****
Reference
Date (must be pre-application submission)
22/09/2023
Details of the pre-application advice received
Informed of survey, informed of roofers invoice, photographs shown and work to be carried out
Authority Employee/Member
With respect to the Authority, is the applicant and/or agent one of the following: (a) a member of staff
(b) an elected member
(c) related to a member of staff (d) related to an elected member
It is an important principle of decision-making that the process is open and transparent.
For the purposes of this question, "related to" means related, by birth or otherwise, closely enough that a fair-minded and informed observer, having
considered the facts, would conclude that there was bias on the part of the decision-maker in the Local Planning Authority.
Do any of the above statements apply?
○ Yes⊙ No
Ownership Certificates and Agricultural Land Declaration
Certificates under Article 14 - Town and Country Planning (Development Management Procedure) (England) Order 2015 & Regulation 6 - Planning (Listed Buildings and Conservation Areas) Regulations 1990
Please answer the following questions to determine which Certificate of Ownership you need to complete: A, B, C or D.
Is the applicant the sole owner of all the land to which this application relates; and has the applicant been the sole owner for more than 21 days? O No
Is any of the land to which the application relates part of an Agricultural Holding? ○ Yes ○ No

Certificate Of Ownership - Certificate A I certify/The applicant certifies that on the day 21 days before the date of this application nobody except myself/the applicant was the owner* of any part of the land or building to which the application relates, and that none of the land to which the application relates is, or is part of, an agricultural holding** * 'owner' is a person with a freehold interest or leasehold interest with at least 7 years left to run. ** 'agricultural holding' has the meaning given by reference to the definition of 'agricultural tenant' in section 65(8) of the Act. NOTE: You should sign Certificate B, C or D, as appropriate, if you are the sole owner of the land or building to which the application relates but the land is, or is part of, an agricultural holding. Person Role O The Agent Title Mrs First Name Charlotte Surname Jobse **Declaration Date** 16/10/2023

Declaration

✓ Declaration made

I/We hereby apply for Householder planning & listed building consent as described in the questions answered, details provided, and the accompanying plans/drawings and additional information.

I/We confirm that, to the best of my/our knowledge, any facts stated are true and accurate and any opinions given are the genuine opinions of the person(s) giving them.

I/We also accept that, in accordance with the Planning Portal's terms and conditions:

- Once submitted, this information will be made available to the Local Planning Authority and, once validated by them, be published as part of a public register and on the authority's website;