



Distance from property to hedgerow is 2ft making property maintenance to windows, fascias, gutter etc not possible as ladder/scaffold access is restricted.



